

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD

5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEX SINGAPORE 069110 INV No. AC2303619

INV Date 08/06/2023

Reference CS3/EQI23005579/Kqp3m4

Code EQI

PROFESSIONAL SERVICE FEE

Vehicle No. SGV 635U

Insured Veh. YP 8277K

Claim No. DM23HO01173

Policy No.

Accident Date 31/05/2023

Inspection Date 05/06/2023

Description	Total
Pre-Repair Survey	100.00
Subtotal	100.00
GST (8%)	8.00
Grand Total	108.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

SML



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT							
	EQ INSURANCE C	OMPANY LTD	R	ef:	CS3/EQI23005579/Kqp3m4		
	5 MAXWELL ROAD #17-00 TOWER BL MND COMPLEXSI	OCK		ate:	08/06/2023		
				ode:			
1.	Policy Particulars :- (THIRD PARTY CLAIM)						
	Insured Veh.	YP 8277K	Veh. Inspected		SGV 635U		
	Policy No.		Coverage (\$)		0.00		
	Claim No.	DM23HO01173	Excess (\$)		0.00		
	Assign From	JOSEPHINE WONG	Assign Date		01/06/2023		
2. Vehicle Particulars & Condition							
	Make & Model	BMW 535I (A)	c.c		2979		
	Engine No.	HIDDEN	Year of Reg.		2010		
	Chassis No.	WBAFR72040C579673	Colour		METALLIC BLACK		
	Odometer	158186 KM	Steering		IN ORDER		
	Brakes	IN ORDER	Modification		SPORTS RIM		
	General	GOOD					
3. Conditions of Tyres							
		Size	Make		Balance		
	R/H Front Tyre	255/35 ZR20	TOURADOR		6 mm		
	L/H Front Tyre	255/35 ZR20	TOURADOR		6 mm		
	R/H Rear Tyre	285/30 ZR20	MICHELIN		8 mm		
	L/H Rear Tyre	285/30 ZR20	MICHELIN		8 mm		
4.		Descripti	on of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.						
5.		Genera	al Information				
	Accident Date	31/05/2023	Inspect Date / Tin	ne	05/06/2023 (10:25 AM)		
	Survey held at	KUM CHEW MOTOR WORKSHO	OP				
		160 SIN MING DRIVE #05-08 SIN MING AUTOCITY SINGAPORE 575722					
5a.	. Remarks						
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000						
5b.	5b. Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days						

Report Ref No. CS3/EQI23005579/Kqp3m4

Inspected By

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGV 635U

INSPECTION
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R













51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933


TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGV 635U

RE-INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

