

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURAN	Re	f:	CS3/LPC23005592/Kny3m4		
	300 BEACH ROAD #17-04/07 THE CO	Da	te:	08/06/2023		
			Co	de:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	YN 9429T	Veh. Inspected		SNH 3552X	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	22/23/23/VC05/027489	Excess (\$)		0.00	
	Assign From	CHARMAINE KONG	Assign Date		01/06/2023	
2.	2. Vehicle Particulars & Condition					
	Make & Model	LEXUS RX200T (A)	c.c		1998	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	JTJZAMCA102007069	Colour		METALLIC BLACK	
	Odometer	105049 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	235/65R18	MICHELIN		8 mm	
	L/H Front Tyre	235/65R18	MICHELIN		8 mm	
	R/H Rear Tyre	235/65R18	MICHELIN		8 mm	
	L/H Rear Tyre	235/65R18	MICHELIN		8 mm	
4.	4. Description of Damages					
	THE VEHICLE SUS	SUSTAINED DAMAGES AT THE N/S FRONT PORTION.				
5. General Information						
	Accident Date	29/05/2023	Inspect Date / Tim	е	05/06/2023 (10:55 AM)	
	Survey held at	TEAM AUTOPRO PTE LTD				
		160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722				
5a. Remarks						
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC23005592/Kny3m4

Inspected By

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser