Blk 416 Pasir Ris Dr 6 #08-235, Singapore 510416 Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783 Reg No: 201000228E

VEHICLE INSPECTION REPORT

To: Saleh Bin Mohamad

Date

: 4 April 2023

C/o: Yap Lee Motor

Our ref

: YL/03/2303/TP

No. 1 Kaki Bukit Ave 6

#01-26 AutoBay, Singapore 417883

Accident Date

24 March 2023

Type of Survey : Third Party

Inspection Date

28 March 2023

Repairer Name

Yap Lee Motor

No. 1 Kaki Bukit Ave 6

#01-26 AutoBay, Singapore 417883

PARTICULARS OF VEHICLE

Registration No

: SMQ 3499 G

Year / Capacity:

•

12

2019 / 1591 cc

Make / Model

: Kia Cerato

Colour

Black

Chassis No

: KNAF3416MK5051940

Mileage

49900

Engine No

: G4FGKH748534

CONDITION OF TYRES

		Make	Size	Thread Balance	Rim
Front Nearside	:	Kumho	205/55 R16	5 mm	Sport
Front Offside	ě	Kumho	205/55 R16	5 mm	Sport
Rear Nearside	:	Kumho	205/55 R16	5 mm	Sport
Rear Offside	2	Kumho	205/55 R16	5 mm	Sport

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the rear portion. (Details refer to the photographs attached)

Enclosed number of photographs:

118

copies

REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not given authorization and instruction to the repairer to proceed with the repair.

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a Lump Sum of \$8,100.00 on a contractual basis.

Under normal circumstances, the repair period would be about 6 (Six) working days.

Page 1

C L APPRAISER PTE LTD

Vehicle Registration No.: SMQ 3499 G

Our Ref No.:

YL/03/2303/TP

1 F 2 F 2 F 1	Rear boot lid Rear boot hinges Rear boot lamps Rear boot logo Rear boot rubber Rear boot "CERATO" emblem Rear boot "C&C" emblem Rear taillamps Rear end panel	Damage Intact Damage Necessary Necessary Necessary Necessary Damage	\$ \$ \$ \$ \$ \$ \$	1,497.00 250.00 800.40 80.80 200.70	\$ \$ \$	1,497.00 1086 × nn 800.40 × nn 80.80 ✓
1 F 2 F 2 F 1	Rear boot lid Rear boot hinges Rear boot lamps Rear boot logo Rear boot rubber Rear boot "CERATO" emblem Rear boot "C&C" emblem Rear taillamps Rear end panel	Intact Damage Necessary Necessary Necessary Necessary	\$ \$ \$	250.00 800.40 80.80	\$	× nn 800.40 × nn
2 F 2 F 1 F 1 F 1 F 2 F 1 F 1 F 1 F 1 F 1 F 1 F 2 F	Rear boot hinges Rear boot lamps Rear boot logo Rear boot rubber Rear boot "CERATO" emblem Rear boot "C&C" emblem Rear taillamps Rear end panel	Intact Damage Necessary Necessary Necessary Necessary	\$ \$ \$	250.00 800.40 80.80	\$	× nn 800.40 × nn
2 F 2 F 1 F 1 F 1 F 2 F 1 F 1 F 1 F 1 F 1 F 1 F 2 F	Rear boot hinges Rear boot lamps Rear boot logo Rear boot rubber Rear boot "CERATO" emblem Rear boot "C&C" emblem Rear taillamps Rear end panel	Intact Damage Necessary Necessary Necessary Necessary	\$ \$ \$	250.00 800.40 80.80	\$	$800.40 \times nn$
2 H 1 H 1 H 1 H 2 H 1 H 1 H 1 H 1 H 1 H 1 H 1 H 1 H 1 H 1	Rear boot lamps Rear boot logo Rear boot rubber Rear boot "CERATO" emblem Rear boot "C&C" emblem Rear taillamps Rear end panel	Damage Necessary Necessary Necessary	\$ \$ \$	80.80	\$	
1 H 1 H 1 H 2 H 1 H 1 H 1 H 1 H 1 H 1 H 1 H 1 H 1 H 1	Rear boot logo Rear boot rubber Rear boot "CERATO" emblem Rear boot "C&C" emblem Rear taillamps Rear end panel	Necessary Necessary Necessary	\$ \$			80.80 🗸
1 H 1 H 2 H 1 H 1 H 1 H 1 H 1 H 1 H 1 H 2 H	Rear boot rubber Rear boot "CERATO" emblem Rear boot "C&C" emblem Rear taillamps Rear end panel	Necessary Necessary Necessary		200.70	\$	
1 H 1 H 2 H 1 H 1 H 1 H 1 H 1 H 1 H 1 H 2 H	Rear boot "CERATO" emblem Rear boot "C&C" emblem Rear taillamps Rear end panel	Necessary Necessary	\$			200.70 🗸
1 H 2 H 1 H 1 H 1 H 1 H 2 H	Rear boot "C&C" emblem Rear taillamps Rear end panel	Necessary		91.00	\$	91.00 🗸
2 H 1 H 1 H 1 H 1 H 1 H 2 H	Rear taillamps Rear end panel	-	\$	62.00	\$	62.00 ✓
1 H 1 H 1 H 1 H 1 H 2 H	Rear end panel		\$	1,068.00	\$	1,068.00 × nn
1 H 1 H 1 H 1 H 2 H		Damage	\$	589.00	\$	589.00 ✓
1 H 1 H 1 H 2 H	Rear end panel inner garnish	Damage	\$	155.00	\$	155.00 🗸
1 I 1 I 2 I	Rear smart keyless sensor -outer	Damage	\$	185.00	\$	185.00 46 ✓
1 I 2 I	Rear smart keyless sensor -inner	Damage	\$	180.00	\$	180.00 95 ✓
2 I	Rear bumper	Damage	\$	869.70	\$	869.70 688 v
	Rear bumper brackets	Damage	\$	178.00	\$	178.00 ✓
	Rear bumper lower diffuser	Damage	\$	420.50	\$	420.50 285 🗸
2 I	Rear bumper reflectors	Damage	\$	468.00	\$	468.00 ✓
	Rear bumper reflector covers	Damage	\$	210.00	\$	210.00 🗸
	Rear bumper reinforcement	Damage	\$	389.00	\$	389.00 ✓
	Rear bumper reinforcement stays	Damage	\$	321.60	\$	321.60 175 🗸
	Rear bumper side retainers	Necessary	\$	160.40	\$	160.40 🗸
	Rear bumper n/s undercover	Damage	\$	125.00	\$	125.00 🗸
	Rear floor board	Damage	\$	291.00	\$	291.00 × nn
	Rear tools sponge tray	Damage	\$	175.00	\$	175.00 🗸
			\$	8,767.10	\$	8,517.10 5258.
		Less 10%	\$	876.71	\$	851.71 -20%
	Total Cost - List Items		\$	7,890.39	\$	7,665.39 4207.
	SPECIAL NETT ITEMS					
1	Rear bumper clip (1 set)	Necessary	\$	60.00	\$	60.00 <mark>30</mark>
	Rear reverse sensor (1 set)	Damage	\$	350.00	\$	350.00 200
	Rear bumper reflector protector set -carbon	Damage	\$	180.00	\$	180.00 50
	Total Cost - Special Nett items		-\$		\$	590.00
	Total Con Sharmt Line years		-			280

Total cost of parts

\$ 8,480.39	\$ 8,255.39



Vehicle Registration No.: SMQ 3499 G

Our Ref No.:

YL/03/2303/TP

S/No	Description		Repairer's		Revised	
5/110	Description		Estimate	Amount		
	Total cost of parts c/f	\$	8,480.39	\$	8,255.39	
	<u>LABOUR</u>					
1	To remove, refit, replaced damaged lamps and check up rear electrical wiring	\$	80.00	\$	50.00 30	
2	To remove and refit inner garnishes, inner trim to assist repair.	\$	150.00	\$	120.00 80	
3	To remove and refit rear reverse sensor.	\$	120.00	\$	80.00 3	
4	To transfer boot lid mechanism and wiring assembly to assist repair.	\$	80.00	\$	80.00 50	
5	To apply undercoating on repaired and replaced panel.	\$	100.00	\$	90.00 30	
6	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld; re-align body structure and damaged consistent to the accident.	\$	1,000.00	\$	750.00 🗸	
7	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$	1,000.00	\$	660.00 ✓	
					1630	
	GRAND TOTAL	\$	11,010.39	\$	10,085.39	
			6117.	12	•	
	6 day	S	L/S - 4		69	