

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI23005609/NNY3Q2**Date:** 11/07/2023**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MS003382	
Claimant Vehicle No :	SHA2552K	Insured Vehicle No :	SMK3633S	
Date of Loss:	26/05/2023	Nature of Claim:	TP	Claim No: M2303226

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA2552K	Engine No:	G4LEJU032200
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Chassis No:	KMHC851CVKU114715
Reg. Date:	08/10/2018 (Man. Year: 2018)	Odometer:	627227 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 8 mm	Rear Left Side:	West Lake 9 mm
Front Right Side:	West Lake 8 mm	Rear Right Side:	West Lake 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,270.48	4,037.28	1,233.20	23.40
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	2,170.00	1,570.00	600.00	27.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,451.48	5,618.28	1,833.20	24.60
Approved Total (Overridden) (S\$)		4,500.00		
(S\$)	7,451.48	4,500.00	2,951.48	39.61
+ GST 8.00/8.00% (S\$)	596.12	360.00	236.12	39.61
Nett Amount (S\$)	8,047.60	4,860.00	3,187.60	39.61

INSPECTION

Date of Assignment:	05/06/2023	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	05/06/2023	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Jul 2023)
Parts:	143	HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA2552K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	459.40 FL	*459.40 FL
2	1		*REAR BUMPER CENTRE MOULDING	Cracked	451.25 FL	*451.25 FL
3	1		*REAR BUMPER REINFORCEMENT	Serviceable	394.80 FL	*- FL
4	2		*REAR BUMPER REINFORCEMENT STAY LH /RH	Serviceable	276.20 FL	*- FL
5	1		*REAR BUMPER LOWER MOULDING	Deformed	155.00 FL	*155.00 FL
6	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
7	1		*REAR BUMPER TOW HOOK COVER	Serviceable	98.80 FL	*- FL
8	1		*REAR BUMPER FOG LAMP	Cracked	201.50 FL	*201.50 FL
9	2		*REAR BUMPER NUMBER LAMP LH/RH	Serviceable	170.60 FL	*- FL
10	1		*REAR SMART KEY SENSOR	Serviceable	40.50 FL	*- FL
11	2		*REAR BUMPER BRACKET LH/RH	Serviceable	111.60 FL	*- FL
12	1		*BOOTLID COVER	Dented	2,549.70 FL	*2,549.70 FL
13	1		*BOOTLID LAMP RH	Deformed	822.00 FL	*822.00 FL
14	1		*BOOTLID LOCK UPPER	Serviceable	224.00 FL	*- FL
15	1		*BOOTLID H EMBLEM	Necessary	28.00 FL	*28.00 FL
16	1		*BOOTLID HYBRID EMBLEM	Necessary	24.30 FL	*24.30 FL
17	1		*BOOTLID IONIQ EMBLEM	Necessary	31.20 FL	*31.20 FL
18	1		*REAR BUMPER MAT	Necessary	50.00 FS	*50.00 FS
19	1		*REAR BUMPER NUMBER PLATE W/HOLDER	Cracked	55.00 FS	*55.00 FS
20	1		*REAR BUMPER REVERSE SENSOR	Serviceable	180.00 FS	*- FS
21	1		*BOOTLID APP STICKER	Necessary	40.00 FS	*40.00 FS
22	1		*BOOTLID COMFORT LOGO/TEL NUMBER STICKER	Necessary	60.00 FS	*60.00 FS
23	2		*SEALLANT WINDSCREEN	Necessary	46.00 FL	*46.00 FL
Sub Total (\$\$)						6,491.85 4,995.35
- List Item Discount on L Items 20.00/20.00% (\$\$)						1,221.37 958.07
Total Parts (\$\$)						5,270.48 4,037.28

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,100.00	700.00
2	SPRAY PAINTING	New	600.00	500.00
3	CHECK WIRING AND LIGHTING	New	60.00	30.00
4	REMOVE/REFIX REAR WINDSCREEN GLASS UPPER/LOWER	New	200.00	200.00
5	REMOVE/REFIX REVERSE SENSOR	New	60.00	30.00
6	TUFF COATING	New	90.00	50.00
7	TOWING FEE	New	60.00	60.00
Gross Labour Cost (\$\$)			2,170.00	1,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >