



Your Ref : DMPC2300365H/02/CT

Date: 08<sup>th</sup> June 2023

Our Ref : CS/ICS23005621/Uny3e2

**M/s ECICS Ltd**

10 Eunos Road 8

Singapore Post Centre #09-04A

Singapore 408600

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE FBC 9234T  
INSURED VEHICLE: SKW 8221A  
ACCIDENT ON 13/05/2023**

Instruction was received to inspect the vehicle Reg. No. FBC 9234T. The inspection was conducted on 05/06/2023 at the premises of M/s Ban Hock Hin Co. Pte Ltd, Blk 8 Defu South Street 1, #04-28 JTC Defu Industrial City, Singapore 533758.

The following vehicle information was recorded:

Registration Number	: FBC 9234T
Make/Model	: Yamaha FZ150I
Year of Registration	: 2008
Body Colour	: Green
Chassis Number	: PMYKG025080002475
Engine Capacity	: 150 cc

The vehicle sustained damages at the n/s body and o/s body. The body structure affected due to collision. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 5,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 2,245.00)
Nett Liability	<u>S\$ 2,755.00</u> =====

Vehicle Inspected By:



CHUA KANG SENG  
Licensed Appraiser



K.K.LAU  
MSc(Eng M), B Eng(Hons), PEng(UK),  
MASME(USA), B Bus(Aust), MBA(UK),  
IEng(UK), MIIE(mech), MinstAEA, MFIEA,  
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),  
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),  
Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.