

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS23005629/RQY3M4**Date:** 06/07/2023REFERENCE

Handling Insurer: ECICS Limited Policy No: MPC23P00116800
Claimant Vehicle No : SLL2345L **Insured Vehicle No :** SLV2992R
 Date of Loss: 27/05/2023 Nature of Claim: TP Claim No: DMPC2300426H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLL2345L**
 Make & Model: MAZDA CX-9, 2.5 TURBO 2WD (A) Engine No: PY30975331
 Reg. Date: 17/03/2020 (Man. Year: 2019) Chassis No: JM6TC2WLAK0319043
 Colour: Red Odometer: 101743 km
 Engine Capacity: 2488 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/50R20 Rear Tyre Size: 255/50R20
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,888.50	1,454.80	433.70	22.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	650.00	430.00	220.00	33.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,538.50	1,884.80	653.70	25.75
+ GST 8.00/8.00% (S\$)	203.08	150.78	52.30	25.75
Nett Amount (S\$)	2,741.58	2,035.58	706.00	25.75

INSPECTION

Date of Assignment: 05/06/2023
 Date Inspected: 08/06/2023 Inspected At: HIN LUNG WORKSHOP
 BLK 1008 BUKIT MERAH LANE 3
 #01-20 SINGAPORE 159722
 Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Jul 2023)
Parts:	M1-SUV	MAZDA CX-9 2.5 TURBO 2WD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLL2345L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,495.50 F	*1,495.50 FL
2	1		*REAR BUMPER SIDE RETAINER LH	Not Necessary	35.00 F	*- FL
3	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	35.00 F	*- FL
4	10		*BUMPER CLIPS	Necessary	55.00 F	*55.00 FL
5	1		*REAR LOWER CHROME	Cracked	268.00 F	*268.00 FL
						F=Franchise part. L=ListItemDisc.
Sub Total (S\$)					1,888.50	1,818.50
- List Item Discount on L Items 0.00/20.00% (S\$)					0.00	363.70
Total Parts (S\$)					1,888.50	1,454.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE NEW PARTS, REMOVE/REFIT ALL ATTACHMENT PARTS TO FACILITATE REPAIR	New	300.00	200.00
2	SPRAY PAINT ON THE EFFECTED AREAS WITH 2K PAINT	New	300.00	200.00
3	CHECK WIRING AND PROPER FUNCTIONING	New	50.00	30.00
Gross Labour Cost (S\$)			650.00	430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >