

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23005649/UVP3E2**Date:** 14/06/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNW00004282301		
Claimant Vehicle No :	JUD1938	Insured Vehicle No :	SJN6938M		
Date of Loss:	23/05/2023	Nature of Claim:	TP	Claim No:	SNM23D203836/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	JUD1938	Engine No:	G3G5E193991
Make & Model:	YAMAHA LC135, 134cc	Chassis No:	PMYUG0810L0193951
Reg. Date:	24/08/2020 (Man. Year: 2020)	Odometer:	71292 km
Colour:	Blue		
Engine Capacity:	134 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	70-90-17	Rear Tyre Size:	80-90-17
Front Left Side:	Maxxis 6 mm	Rear Left Side:	Maxxis 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,353.70	5,222.60	1,131.10	17.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	980.00	650.00	330.00	33.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	7,333.70	5,872.60	1,461.10	19.92

INSPECTION

Date of Assignment:	05/06/2023		
Date Inspected:	05/06/2023	Inspected At:	Erofia Motor Trading Pte Ltd (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-62 Singapore 417883
Estimated Period of Repair:	0.0 days		

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

TOTAL LOSS ASPECT

Market Value (RM) : \$5,700.00÷3.3=\$1,700.00
OMV : \$-
Salvage Value (1) : \$100.00
Quota Premium Paid : \$-
COE Rebate (2) : \$-
Total Rebate (1) + (2) = : \$-

The total amount incurred will be Market Value \$1700.00 minus Salvage Value\$100.00
= \$1,600.00

In view of the above, the vehicle is uneconomical to be repaired, you are advised
to invite tender for the wreck.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 14 Jun 2023)	
Parts:	N/A	YAMAHA LC135 134cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for JUD1938)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT FORK TUBE ASSY	Bent / Twisted	640.00 FL	*640.00 FL
2	1		*FORK UNDER BRACKET	Bent	185.00 FL	*185.00 FL
3	1		*FRONT WHEEL RIM	Cracked	380.00 FL	*380.00 FL
4	1		*FRONT RIM SHAFT	Bent	45.00 FL	*45.00 FL
5	1		*FRONT RIM BEARING	Damaged	38.00 FL	*38.00 FL
6	1		*FRONT BRAKE DISC	Warped	185.00 FL	*185.00 FL
7	1		*HANDLE BAR	Bent	88.00 FL	*88.00 FL
8	1		*SET HANDLE-BAR ENDS	Cut	74.00 FL	*74.00 FL
9	1		*SET HAND GRIP	Not Necessary	55.00 FL	*- FL
10	1		*HANDLE BAR INNER BRACKET	Repair	78.00 FL	*- FL
11	1		*HEADLAMP ASSY	Scratched	485.00 FL	*485.00 FL
12	1		*SET SIDE MIRRORS	Cut	110.00 FL	*110.00 FL
13	1		*BRAKE LEVER	Cut	32.00 FL	*32.00 FL
14	1		*SET FRONT SIGNALS	Cracked	140.00 FL	*140.00 FL
15	1		*FRONT SIGNAL LOWER GARNISH	Cracked	105.00 FL	*105.00 FL
16	1		*SET FAIRING ASSY	Cracked	525.00 FL	*525.00 FL
17	1		*FRONT INNER COVER	Cracked	250.00 FL	*250.00 FL
18	1		*SET SIDE LOWER COVER - MATT	Distorted	160.00 FL	*160.00 FL
19	1		*RADIATOR	Distorted	580.00 FL	*580.00 FL
20	1		*FRONT FOOTREST BRACKET	Bent	65.00 FL	*65.00 FL
21	1		*FRONT FOOTREST RUBBERS (2PCS)	Torn (1Pc Only)	70.00 FL	*35.00 FL
22	1		*BRAKE PEDAL	Bent	42.00 FL	*42.00 FL
23	1		*GEAR PEDAL	Not Necessary	125.00 FL	*- FL
24	2		*REAR FOOTRESTS	Not Necessary	80.00 FL	*- FL
25	2		*REAR FOOTREST BRACKETS	Not Necessary	156.00 FL	*- FL
26	1		*EXHAUST ASSY	Dented	685.00 FL	*685.00 FL
27	1		*EXHAUST END CAP	Cut	75.00 FL	*75.00 FL
28	1		*EXHAUST PROTECTOR	Cut	55.00 FL	*55.00 FL
29	1		*SET REAR SIGNALS	Not Necessary	140.00 FL	*- FL
30	1		*BASKET	Bent	135.00 FL	*135.00 FL
31	1		*SET NUMBER PLATE	Bent / Necessary	38.00 FS	*30.00 FS
32	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
33	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
34	1		*SET STEERING CONE	Necessary	185.00 FS	*60.00 FS
35	1		*SET STICKER	Necessary	180.00 FS	*100.00 FS
36	1		*REAR BOX	Cut	480.00 FS	*280.00 FS
37	1		*REAR BOX BRACKET	Bent	180.00 FS	*150.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,932.00	5,734.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	578.30	511.40
Total Parts (\$\$)	6,353.70	5,222.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
2	TO PROVIDE LABOUR	New	480.00	350.00
3	TO RE-ALIGN BODY FRAME	New	420.00	300.00
Gross Labour Cost (S\$)			980.00	650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >