

ESTIMATE TO REPAIR

VEHICLE NO. : GBF 802 Y
 MAKE : TOYOTA
 MODEL : HIACE VAN TURBO 5 DR MANUAL
 YEAR : 2016
 CHASSIS NO : JTFHT02P100199006

SURVEYOR NAME	:
DATE OF SURVEY	:
TIME OF SURVEY	:

DATE : 5-Jun-23
 DATE OF ACCIDENT : 3-Jun-23
 THIRD PARTY REF : GBF 3605 E
 THIRD PARTY REF : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	o/s front door				\$ 1,999.70
1 pc	o/s front door power window motor				\$ 979.50
1 pc	o/s front door regulator				\$ 271.80
	Less 25%				\$ 3,251.00
					\$ 812.75
					\$ 2,438.25
1 pc	o/s front door body leather	S.Nett			\$ 30.00
1 pc	o/s front door DHL logo	S.Nett			\$ 180.00
1 pc	o/s front rim	S.Nett			\$ 200.00
	To putty & spray paint				\$ 500.00
	To check wheel alignment				\$ 60.00
	To anti rust				\$ 50.00
	Labour charges				\$ 400.00
TG/VL	TOTAL				\$ 510.00

*NOT WITHHOLD
 1 Day &
 Return After Rain
 4 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

TG/VL	TOTAL				\$ -
-------	-------	--	--	--	------