

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBF 9292J

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	HANDLE BAR	BENT	105.00	105.00
1	BALANCER	SCRATCHED	65.00	35.00
1	MIRROR	BROKEN	65.00	65.00
1	LEVER	CUT	75.00	75.00
1	SET COVER	TO REPAIR SEE LABOUR	480.00	-
1	HEADLIGHT	CRACKED	105.00	105.00
1	SIGNAL LIGHT FRONT	CRACKED	70.00	70.00
1	FORK	SERVICEABLE	240.00	-
1	FORK LOWER BRACKET	NOT NECESSARY	180.00	-
1	STEERING CONE	NECESSARY	120.00	60.00
1	FRONT MUDGUARD	CRACKED	95.00	95.00
1	FRONT FOOTREST RH	CUT	58.00	58.00
1	REAR FOOTREST RH	TORN	58.00	58.00
1	EXHAUST COVER	BENT	115.00	115.00
1	FOOT PEDAL	TO REPAIR SEE LABOUR	85.00	-
1	EXHAUST PIPE	TO REPAIR SEE LABOUR	340.00	-
1	LAMP STAY	BENT	115.00	115.00
1	HELMET	CUT/CRACKED	85.00	85.00
1	BOX	CUT	180.00	180.00
1	REAR FOOTREST LH	TORN	58.00	58.00
	LESS 10% DISCOUNT		-	-127.90
			2,694.00	1,151.10
	<u>LABOUR</u>			
	BODY FRAME SPRAY. (NPA)	NOT NECESSARY	-	-
	TOWING.		50.00	50.00

Report Ref No. CS/INC23005682/Uny3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	LABOUR. INCLUSIVE OF THE REPAIR OF SET COVER, FOOT PEDAL AND EXHAUST PIPE.		350.00	300.00
			400.00	350.00
	GRAND TOTAL		3,094.00	1,501.10

RECOMMENDED COST OF LUMP SUM REPAIRS		1,200.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. CS/INC23005682/Uny3m4

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser