

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	INCOME INSURAN	NCE LTD	Re	ef:	CS3/INC23005683/Tny3m4	
	75 BRAS BASAH FINCOME CENTRE	ROAD SINGAPORE 189557	Da	ate:	12/06/2023	
	ATTN: RODERIC Y	/UEN	Co	ode:	INC	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SMW 4125Y	Veh. Inspected		SLU 462Y	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1226315-001	Excess (\$)		0.00	
	Assign From	JULIET KOH	Assign Date		06/06/2023	
2.	Vehicle Particulars & Condition					
	Make & Model	MAZDA 3	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	JM6BN24A8J0181208	Colour		BLUE	
	Odometer	112344 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	225/45R18	YOKOHAMA		6 mm	
	L/H Front Tyre	225/45R18	YOKOHAMA		6 mm	
	R/H Rear Tyre	225/45R18	YOKOHAMA		6 mm	
	L/H Rear Tyre	225/45R18	YOKOHAMA		6 mm	
4. Description of Damages						
	THE VEHICLE SUS	STAINED DAMAGES AT THE FRONT N/S PORTION.				
5.	General Information					
	Accident Date	05/06/2023	Inspect Date / Tin	ne	06/06/2023 (12:30 PM)	
	Survey held at	held at GARAGE 13 PTE LTD				
		8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE.				
5a.		Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/INC23005683/Tny3m4

Inspected By

MOHAMAD TAUFIKH M.MATAI, AMSAE-A K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor