

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	INCOME INSURAN	ICE LTD	Ref:	CS3/INC23005684/Tvy3e2	
	75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557		Date:	12/06/2023	
	ATTN: RODERIC Y	'UEN	Code:	INC	
1.	. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SMD 923L	Veh. Inspected	SMT 2880D	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	MT/1225696-002	Excess (\$)	0.00	
	Assign From	JULIET KOH	Assign Date	06/06/2023	
2. Vehicle Particulars & Condition					
	Make & Model	KIA CERATO	c.c	1591	
	Engine No.	HIDDEN	Year of Reg.	2020	
	Chassis No.	KNAF3416ML5070236	Colour	GREY	
	Odometer	100128 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	205/55 R16	MICHELIN	6 mm	
	L/H Front Tyre	205/55 R16	MICHELIN	6 mm	
	R/H Rear Tyre	205/55 R16	MICHELIN	6 mm	
	L/H Rear Tyre	205/55 R16	MICHELIN	6 mm	
4. Description of Damages					
	THE VEHICLE SUS	STAINED DAMAGES AT THE FRONT O/S PORTION.			
5.	General Information				
	Accident Date	31/05/2023	Inspect Date / Time	06/06/2023 ( 12:30 PM )	
	Survey held at	GARAGE 13 PTE LTD			
		8 KAKI BUKIT AVE 4 #03-46 PREMIER SINGAPORE 415875			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/INC23005684/Tvy3e2

Inspected By

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**Automotive Assessor**