



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBR 7875C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT RIM SHAFT	NOT NECESSARY	98.00	-
1	SET FRONT SIDE COVER - MATT	CUT	260.00	260.00
1	SIDE MIRROR N/S	CUT	180.00	95.00
1	HANDLE-BAR	NOT NECESSARY	175.00	-
1	SET HANDLE-BAR BALANCER	NOT NECESSARY	125.00	-
1	SET HAND GRIP	NOT NECESSARY	95.00	-
1	BRAKE LEVERS N/S	CUT	180.00	60.00
2	FOOTSTEP PANEL - L/R/H (O/S CUT)	O/S NOT CONSISTENT WITH THE IMPACT / N/S CUT	510.00	160.00
2	FOOTSTEP LOWER PANEL - L/R/H (O/S CUT)	O/S NOT CONSISTENT WITH THE IMPACT / N/S CUT	680.00	180.00
1	DROVE BELT COVER	NOT NECESSARY	285.00	-
1	AIR FILTER COVER	NOT NECESSARY	165.00	-
1	SIDE STAND	TO REPAIR SEE LABOUR	105.00	-
1	MAIN STAND	TO REPAIR SEE LABOUR	155.00	-
2	REAR FOOTREST - L/R/H (CUT)	NOT CONSISTENT WITH THE IMPACT	360.00	-
1	SET FAIRING COVER	TO REPAIR SEE LABOUR	1,450.00	-
1	SIDE COVER LH	CRACKED	210.00	210.00
	LESS 10% DISCOUNT		-503.30	-96.50
			4,529.70	868.50
<u>SPECIAL NETT ITEMS</u>				
2	FORK OILS (SN)	NOT NECESSARY	30.00	-
2	FORK OIL SEALS (SN)	NOT NECESSARY	56.00	-
1	SET STEERING CONE (SN)	NOT NECESSARY	120.00	-
1	REAR BOX (SN)	NOT NECESSARY	480.00	-
1	REAR BOX BRACKET (SN)	NOT NECESSARY	180.00	-

Report Ref No. CS/INC23005688/Uqy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	STICKER (SN) <u>LABOUR</u> TO CHECK WIRING AND RESET HEADLAMP FOCUSING. TO REPAIR FRONT FORK. TO PROVIDE LABOUR. INCLUSIVE OF THE REPAIR OF SIDE STAND, MAIN STAND AND 1 SET FAIRING COVER. TO SPRAY PAINTING.	NECESSARY	120.00	80.00
			986.00	80.00
		NOT NECESSARY NOT NECESSARY	80.00	-
			380.00	-
			450.00	250.00
			300.00	300.00
	1,210.00	550.00		
GRAND TOTAL			6,725.70	1,498.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,100.00

Report Ref No. CS/INC23005688/Uqy3e2

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.