



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD  
INCOME CENTRESINGAPORE 189557

ATTN: CYNTHIA ANG

Ref: CS/INC23005690/Aqy3m4

Date: 24/07/2023

Code: INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                |                |            |
|--------------|----------------|----------------|------------|
| Insured Veh. | SMM 2760D      | Veh. Inspected | QS 6806Q   |
| Policy No.   |                | Coverage (\$)  | 0.00       |
| Claim No.    | MT/1225246-002 | Excess (\$)    | 0.00       |
| Assign From  | JULIET KOH     | Assign Date    | 06/06/2023 |

### 2. Vehicle Particulars & Condition

|              |                   |              |            |
|--------------|-------------------|--------------|------------|
| Make & Model | HYUNDAI STAREX    | c.c          | 2497       |
| Engine No.   | HIDDEN            | Year of Reg. | 2012       |
| Chassis No.  | KMJWA37KMCU513103 | Colour       | WHITE      |
| Odometer     | 182418 KM         | Steering     | IN ORDER   |
| Brakes       | IN ORDER          | Modification | SPORTS RIM |
| General      | GOOD              |              |            |

### 3. Conditions of Tyres

|                | Size        | Make    | Balance |
|----------------|-------------|---------|---------|
| R/H Front Tyre | 215/70 R16C | HANKOOK | 6 mm    |
| L/H Front Tyre | 215/70 R16C | HANKOOK | 6 mm    |
| R/H Rear Tyre  | 215/70 R16C | HANKOOK | 6 mm    |
| L/H Rear Tyre  | 215/70 R16C | HANKOOK | 6 mm    |

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

|                |   |                     |                         |
|----------------|---|---------------------|-------------------------|
| Accident Date  | 26/05/2023  | Inspect Date / Time | 06/06/2023 ( 02:03 PM ) |
| Survey held at | SM AUTOMOTIVE<br>BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883 |                     |                         |

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days