

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/MSG23005710/KQY3M4  
**Date:** 16/06/2023REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001441803
<b>Claimant Vehicle No :</b>	SJN9374U	<b>Insured Vehicle No :</b>	SKM8977E
Date of Loss:	03/06/2023	Nature of Claim:	TP
		Claim No:	316717

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJN9374U</b>	Engine No:	G4FC9U614272
Make & Model:	HYUNDAI HD AVANTE, 1.6 (A)	Chassis No:	KMHDU41BR9U706022
Reg. Date:	05/03/2009 (Man. Year: 2009)	Odometer:	540082 km
Colour:	Metallic Silver		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65R15	Rear Tyre Size:	185/65R15
Front Left Side:	Giti 7 mm	Rear Left Side:	Giti 7 mm
Front Right Side:	Giti 7 mm	Rear Right Side:	Giti 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,503.29	2,196.36	2,306.93	51.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,960.00	750.00	1,210.00	61.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,463.29</b>	<b>2,946.36</b>	<b>3,516.93</b>	<b>54.41</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,350.00</b>		
<b>Nett Amount (S\$)</b>	<b>6,463.29</b>	<b>2,350.00</b>	<b>4,113.29</b>	<b>63.64</b>

INSPECTION

Date of Assignment:	06/06/2023		
Date Inspected:	07/06/2023	Inspected At:	AUTHORIZE WORKSHOP PTE LTD 160 SIN MING DRIVE #03-19, SIN MING AUTOCITY, SINGAPORE 575722
Estimated Period of Repair:	4.0 days		

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 16 Jun 2023)
<b>Parts:</b> 143	HYUNDAI HD AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SJN9374U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Bent	886.00 FL	*886.00 FL
2	1		*REAR BOOT HYUNDAI LOGO	Necessary	32.90 FL	*32.90 FL
3	1		*REAR BOOT LID AVANTE EMBLEM	Necessary	32.50 FL	*32.50 FL
4	1		*REAR BOOT LID S EMBLEM	Necessary	25.60 FL	*25.60 FL
5	1		*REAR BOOT LID REFLECTOR LAMP RH	Cut	126.20 FL	*126.20 FL
6	1		*REAR BOOT MECHANISM LOCK	Repair	168.00 FL	*- FL
7	1		*REAR BOOT LID INNER TRIM BOARD	Serviceable	126.40 FL	*- FL
8	1		*REAR END PANEL	Repair	485.10 FL	*- FL
9	1		*REAR END PANEL TOP GARNISH	Serviceable	89.30 FL	*- FL
10	1		*REAR BOOT WEATHERSTRIP	Serviceable	118.50 FL	*- FL
11	1		*REAR SPARE TIRE PANEL	Repair	825.40 FL	*- FL
12	1		*REAR BOOT LID HINGE SUPPORT SPRING	Serviceable	105.00 FL	*- FL
13	1		*REAR LAMP RH	Mtg Cracked	326.20 FL	*326.20 FL
14	1		*REAR BUMPER	Dented/Cut	582.20 FL	*582.20 FL
15	2		*REAR BUMPER SIDE RETAINER L/R	Serviceable	84.60 FL	*- FL
16	2		*REAR BUMPER BRACKET L/R	Repair	156.60 FL	*- FL
17	1		*REAR BUMPER INNER SPONGE	Cracked	141.40 FL	*141.40 FL
18	1		*REAR BUMPER REINFORCEMENT	Cracked	286.20 FL	*286.20 FL
19	1		*SET REAR BUMPER CLIPS	Necessary	45.00 FS	*45.00 FS
20	1		*SET END PANEL TOP GARNISH CLIPS	Not Necessary	35.00 FS	*- FS
21	1		*SET TRIM BOARD CLIPS	Not Necessary	35.00 FS	*- FS
22	1		*SET REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>4,963.10</b>	<b>2,684.20</b>
<b>- List Item Discount on L Items 10.00/20.00% (S\$)</b>	459.81	487.84
<b>Total Parts (S\$)</b>	<b>4,503.29</b>	<b>2,196.36</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE & REARRANGE ELECTRICAL WIRINGS, CHECK LIGHTINGS	New	80.00	20.00
2	TO REMOVE, TRANSFER BOOT LID COMPONENTS	New	100.00	50.00
3	TO REMOVE, REPAIR & REPLACE DAMAGED BODYPARTS, REALIGN BODYWORK AND WHERE CONSISTENT TO THE ACCIDENT	New	800.00	400.00
4	PUTTY AND RESPRAY PAINTING ON AFFECTED PORTIONS	New	800.00	200.00
5	TO REMOVE & RENEW REVERSE SENSOR	New	100.00	50.00
6	RUST PROOFING ON AFFECTED PORTIONS	New	80.00	30.00
<b>Gross Labour Cost (S\$)</b>			<b>1,960.00</b>	<b>750.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**