

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI23005711/TNY3Q2**Date:** 26/06/2023REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MAA00098
Claimant Vehicle No :	SHC2521P	Insured Vehicle No :	XE8065A
Date of Loss:	05/06/2023	Nature of Claim:	TP
		Claim No:	M2303380

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC2521P	Engine No:	2ZR2F93235
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Chassis No:	JTDKB3FU303090161
Reg. Date:	13/12/2019 (Man. Year: 2019)	Odometer:	358297 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,449.77	7,134.40	4,315.37	37.69
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	2,690.00	1,680.00	1,010.00	37.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,150.77	8,825.40	5,325.37	37.63
Approved Total (Overridden) (S\$)		7,050.00		
(S\$)	14,150.77	7,050.00	7,100.77	50.18
+ GST 8.00/8.00% (S\$)	1,132.06	564.00	568.06	50.18
Nett Amount (S\$)	15,282.83	7,614.00	7,668.83	50.18

INSPECTION

Date of Assignment:	06/06/2023	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	06/06/2023	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	4.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Jun 2023)
Parts:	144	TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC2521P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	586.18 FL	*586.18 FL
2	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	812.89 FL	*- FL
3	2		*FRONT BUMPER REINFORCEMENT ABSOBER LH/RH	Not Necessary	231.40 FL	*- FL
4	1		*FRONT BUMPER CENTRE GRILLE	Not Necessary	301.90 FL	*- FL
5	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	193.18 FL	*- FL
6	10		*FRONT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
7	1		*FRONT BUMPER GARNISH RH	Not Necessary	90.00 FL	*- FL
8	1		*FRONT BUMPER RETAINER LH/RH	N/SNot Necessary / O/SDeformed	181.50 FL	*90.75 FL
9	1		*FRON SUPPORT RAD TOP	Not Necessary	278.68 FL	*- FL
10	1		*FRONT SUPPORT RAD LOWER	Not Necessary	393.20 FL	*- FL
11	2		*FRONT SUPPORT RAD LH/RH	Not Necessary	152.20 FL	*- FL
12	1		*HEADLAMP RH	Cracked	2,735.28 FL	*2,735.28 FL
13	1		*FRONT FENDER RH	Bent	1,111.93 FL	*1,111.93 FL
14	1		*FRONT FENDER EMBLEM RH	Necessary	86.50 FL	*86.50 FL
15	1		*FRONT FENDER SHIELD RH	Torn	198.50 FL	*198.50 FL
16	1		*FRONT WING MIRROR RH	Repeated	139.10 FL	*- FL
17	1		*FRONT WING MIRROR COVER RH	Repeated	14.90 FL	*- FL
18	1		*FRONT DOOR PANEL RH	Bent	1,264.00 FL	*1,264.00 FL
19	1		*FRONT DOOR HINGE UPPERL RH	Not Necessary	91.20 FL	*- FL
20	1		*FRONT DOOR HINGE LOWER RH	Not Necessary	91.20 FL	*- FL
21	1		*FRONT DOOR CHECK RH	Not Necessary	153.52 FL	*- FL
22	1		*FRONT SUSPENSION ARM RH	Not Necessary	637.50 FL	*- FL
23	1		*FRONT BALL JOINT RH	Not Necessary	199.80 FL	*- FL
24	1		*FRONT TIE ROD END RH	Not Necessary	159.30 FL	*- FL
25	1		*FRONT WHEEL ALU RIM RH	Dented	1,555.00 FL	*1,555.00 FL
26	1		*FRONT TYRE RH (80%)	Punctured	216.00 FS	*172.80 FS
27	1		*FRONT KNUCKLE STRG RH	Not Necessary	580.80 FL	*- FL
28	1		*FRONT SHOCK ABSORBER RH	Not Necessary	401.80 FL	*- FL
29	1		*FRONT SHOCK ABSORBER TOP MTG RH	Not Necessary	196.20 FL	*- FL
30	1		*FRONT WIPER SPARE TANK	Not Necessary	486.70 FL	*- FL
31	1		*FRONT DOOR COMFORT LOGO STICKER	Necessary	75.00 FS	*75.00 FS
Supplementary #1						
32	1		*FRONT WING MIRROR RH	Broken	1,390.10 FL	*1,390.10 FL
33	1		*FRONT WING MIRROR COVER RH	Missing	141.90 FL	*141.90 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,169.36	9,429.94
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,719.59	2,295.54
Total Parts (\$\$)	11,449.77	7,134.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,250.00	700.00
2	SPRAY PAINTING	New	900.00	750.00
3	REMOV/REFIX AIR CON AND CHARGE GAS	New	120.00	0.00
4	CHECK WIRING AND LIGHTING	New	60.00	30.00
5	RESET FRONT WHEEL ALIGNMENT	New	90.00	80.00
6	REMOVE/ REFIX FRONT UNDER CARRIAGE	New	120.00	0.00
7	TOWING FEE	New	60.00	60.00
8	REMOVE.REFIX DOOR PART FRT	New	90.00	60.00
Gross Labour Cost (\$\$)			2,690.00	1,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >