

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 6548S

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DENTED/CUT	696.40	495.70
1	LH FRONT BUMPER RETAINER	NECESSARY	187.50	180.00
1	FRONT LH DOOR ASSY	TO REPAIR SEE LABOUR	1,628.00	-
1	FRONT BUMPER LH LOWER GRILLE	SERVICEABLE	320.00	-
2	FRONT LH DOOR HINGES TOP/LOWER 195 EACH	TO REPAIR SEE LABOUR	390.00	-
1	FRONT LH STEP GARNISH	DENTED	322.80	204.90
1	LH HEAD LAMP	CUT	3,094.30	2,536.20
1	FRONT CORNER PANEL LH	TO REPAIR SEE LABOUR	268.00	-
	LESS 25% DISCOUNT		-1,726.75	-854.20
			5,180.25	2,562.60
	SPECIAL NETT ITEMS			
1	FRONT LH TYRE (SN)	SERVICEABLE	125.00	-
1	FRONT LH TYRE RIM (SN)	SERVICEABLE	250.00	-
			375.00	-
	<u>LABOUR</u>			
	TO DISMANTLE / RENEW / REFIT / KNOCKING / STRAIGHTEN THE ACCIDENT DAMAGED PORTION. TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS. INCLUSIVE OF THE REPAIR OF FRONT LH DOOR ASSY, FRONT LH DOOR HINGES TOP/LOWER AND FRONT CORNER PANEL LH.		880.00	400.00
	LABOUR FOR DISMANTLE AND REFIT FRONT DOOR COMPARTMENT / ACCESSORIES.	NOT NECESSARY	100.00	-
	SUPPLY SPRAY PAINT ON ACCIDENT DAMAGE SIDE MATERIAL AND NECESSARY ITEMS.		850.00	200.00
			1,830.00	600.00
	GRAND TOTAL		7,385.25	3,162.60

Report Ref No. CS/INC23005750/Kvp3m4



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		2,500.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. CS/INC23005750/Kvp3m4

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser