



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: RODERIC YUEN

Ref: CS/INC23005750/Kvp3m4

Date: 30/06/2023

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLQ 7148E	Veh. Inspected	PC 6548S
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1226253-001	Excess (\$)	0.00
Assign From	JURAIDAH ABBAS	Assign Date	07/06/2023

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HIACE GL (A)	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KDH2230033306	Colour	SILVER
Odometer	338585 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15X8	GREEN MAX	8 mm
L/H Front Tyre	195 R15X8	GREEN MAX	8 mm
R/H Rear Tyre	195 R15X8	BRIDGESTONE	9 mm
L/H Rear Tyre	195 R15X8	BRIDGESTONE	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	01/06/2023	Inspect Date / Time	15/06/2023 (10:00 AM)
Survey held at	SERVE YOU MOTOR SERVICE BLK 5033 ANG MO KIO IND PK 2 #01-265 SINGAPORE 569536		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**