



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 4172Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT DOOR	DENTED	1,258.20	1,258.20
1	FRONT DOOR LOCK	NOT NECESSARY	198.90	-
1	FRONT DOOR WEATHERSTRIPE	NOT NECESSARY	179.70	-
1	FRONT DOOR LOWER PROTECTOR	CUT	342.60	342.60
1	FRONT DOOR INNER TRIM BOARD	NOT NECESSARY	881.40	-
1	FRONT DOOR GLASS REGULATOR C/W MOTOR	NOT NECESSARY	493.60	-
1	REAR DOOR	DENTED	1,166.40	1,166.40
1	REAR DOOR LOCK	NOT NECESSARY	196.70	-
1	REAR DOOR WEATHERSTRIPE	NOT NECESSARY	187.40	-
1	REAR DOOR LOWER PROTECTOR	CUT	324.50	324.50
1	REAR DOOR INNER TRIM BOARD	NOT NECESSARY	844.40	-
1	REAR DOOR GLASS REGULATOR C/W MOTOR	NOT NECESSARY	487.90	-
1	REAR FENDER	TO REPAIR SEE LABOUR	1,081.40	-
1	REAR FENDER WHEEL ARC GARNISH	CUT	483.10	483.10
1	REAR WHEEL HUB C/W BEARING	NOT NECESSARY	381.90	-
	LESS 10% DISCOUNT		-850.81	-357.48
			7,657.29	3,217.32
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT DOOR LOWER PROTECTOR CLIPS (SN)	NECESSARY	20.00	20.00
1	FRONT DOOR INNER TRIM BOARD CLIPS (SN)	NOT NECESSARY	30.00	-
1	FRONT DOOR BLACK TAPE (SN)	NECESSARY	60.00	60.00
1	REAR DOOR LOWER PROTECTOR CLIPS (SN)	NECESSARY	20.00	20.00
1	REAR DOOR INNER TRIM BOARD CLIPS (SN)	NOT NECESSARY	30.00	-
1	REAR DOOR BLACK TAPE (SN)	NECESSARY	60.00	60.00
1	REAR FENDER WHEEL ARC GARNISH CLIPS (SN)	NECESSARY	20.00	20.00
1	REAR WHEEL RIM (SN)	NOT NECESSARY	850.00	-
1	REAR TYRE (SN)	NOT NECESSARY	280.00	-
			1,370.00	180.00

Report Ref No. CS/AGI23005773/Anp3m4



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>LABOUR</u></b>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR FENDER.		1,000.00	500.00
	SPRAY PAINTING.		1,000.00	600.00
	WIRING.		50.00	30.00
	TO APPLY TUFF COAT.		150.00	60.00
	TO TRANSFER FRONT & REAR DOOR FITTINGS.		300.00	160.00
			2,500.00	1,350.00
	<b>GRAND TOTAL</b>		<b>11,527.29</b>	<b>4,747.32</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,800.00</b>

Report Ref No. CS/AGI23005773/Anp3m4

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.