

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFT 5377D

ty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR DOOR LH	BENT / WARPED	1,236.90	1,236.90
1	REAR DOOR PROTECTOR LH	SCRATCHED	317.10	317.10
1	REAR DOOR INNER RUBBER LH	NOT NECESSARY	299.10	-
1	REAR DOOR INNER GARNISH LH (NPA)	NOT NECESSARY	-	-
1	REAR BUMPER	TO REPAIR SEE LABOUR	1,016.60	-
1	REAR WHEEL HUB BEARING LH	NOT NECESSARY	1,005.50	-
1	REAR SHOCK ABSORBER LH	NOT NECESSARY	227.00	-
	LESS 25% DISCOUNT		-1,025.55	-388.50
			3,076.65	1,165.50
1	REAR WHEEL RIM LH (SN)	CUT	3,641.30	600.00
	LESS 25% DISCOUNT		-910.33	-
			2,730.97	600.00
	SPECIAL NETT ITEMS			
1	FRONT DOOR LH (SN) (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT FENDER LH (SN) (NPA)	NOT NECESSARY	-	-
1	REAR FENDER LH (SN) (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR TYRE LH (SN)	SERVICEABLE	580.00	-
			580.00	-
	<u>LABOUR</u>			
	LABOUR TO REMOVE & REFIT NECESSARY PARTS. INCLUSIVE OF THE REPAIR OF REAR BUMPER, FRONT DOOR LH AND REAR FENDER LH.		1,000.00	500.00
	SPRAY PAINT ON THE AFFECTED AREAS.		1,000.00	800.00
	ANTI-RUST COATING.		120.00	30.00
	TO REMOVE & REFIT UNDERCARRIAGE.	NOT NECESSARY	350.00	-

Report Ref No. CS/AGI23005788/Unp3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	FOUR WHEEL ALIGNMENT.		180.00	60.00
			2,650.00	1,390.00
	GRAND TOTAL		9,037.62	3,155.50

RECOMMENDED COST OF LUMP SUM REPAIRS	2,500.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/AGI23005788/Unp3e2

CHUA KANG SENG