



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SG 6296L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT UPPER DECK WINDSCREEN	CRACKED	4,698.98	4,698.98
1	FRONT LH TREE GUARD	BENT	757.90	757.90
1	FRONT LH UPPERDECK LAMP (ADDITIONAL)	CRACKED	331.76	331.76
	LESS 10% DISCOUNT		-	-578.86
			5,788.64	5,209.78
	<b><u>LABOUR</u></b>			
	SUPPLY SKILLED LABOUR TO REPLACE		2,000.00	1,500.00
	- FRONT UPPER DECK WINDSCREEN			
	- FRONT LH TREE GUARD			
	SUPPLY SKILLED PAINTER & PAINT MATERIAL TO		1,000.00	800.00
	PUTTY, GRINDING & SPRAYPAINT			
	- FRONT LH TOP DOME			
			3,000.00	2,300.00
	<b>GRAND TOTAL</b>		<b>8,788.64</b>	<b>7,509.78</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>7,509.78</b>

Report Ref No. CS/TP23005795/Tqp3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.