

ASS. REC. BY: TaufikREF: CS/TP23005795/TP3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

| | |
|-----|-----|
| | |
| N/S | O/S |
| | |

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Wei Hao Vehicle: IN / OUTVeh No: S96296L Yr Regn: 2021, JanType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MAN A95 C.C. 10518Colour: Green A/C: Insured / Std / NI / NASp. Reading: 142794 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WM1A95E26LF014532Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NI / S/Rim / STD A/Rim orTyre Size: F: 275/70R22.5R: 1 ^ (D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 8 mmL/Bal. 8 mm

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt N/S Rooftop

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. 8/8 mmL/Bal. 8/8 mmD.O.I. 8/6/23Loyang Bus Depot

Date / Time Action / Instruction

Taufikh finalised final fig \$7509.78, 3 days. (Red \$1278.86, 15%)

Date/Time, File Pass to?

☐ : Prel. Report

1) 11/07 Typist

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3Resurvey No. of Trip: 2

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation: \$ + RS. SI

Photos

Others

TOTAL

400

Rep. Format: TPLump Sum / L.B.: 7509.78

Date : 06th June 2023

Quotation No.: Q23-OPS-0902

Go Ahead Singapore Pte Ltd
2 Loyang Way Singapore 508776
Tel: 6812 6458

Dear Mr Tan Tuan Boon, Donald Wong

Quotation: Claims Accident repair job for SG6296L - TPC

We are pleased to submit herein, our quotation for your consideration.

| S/N | Description | UOM | Total Price |
|-------------|--|-------------------|---------------------|
| 1 | Supply skilled labour to replace • Front upper deck windscreen • Front LH tree guard | 1 Job (3 days) | \$ 2,000.00 1500 |
| 2 | Supply skilled painter & paint material to putty, grinding & spraypaint • Front LH top dome | 1 Job (1 day) | \$ 1,000.00 800 |
| 3 | Front upper deck windscreen | 1 PC | \$ 4,698.98 |
| 4 | Front LH tree guard | 1 PC | \$ 757.90 |
| Sub - Total | | | \$ 8,456.88 |

Terms and Conditions:

Payment Terms : 30 days upon invoice
Quotation Validity : 30 days
Lead-Time : 4 working days
Price quoted subject to 8% GST

Yours faithfully

Tien Yong Shun

Tien Yong Shun
Manager

Tan Guan 97495749
WP' 8/6/23 21145
Resurvey new parts
Tan Guan e/khant-wm.
03 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LexBuild Motors Pte. Ltd.

11 Tuas Bay Close, #04-01/02 WEST STAR, Singapore 636996

Tel: (65) 6456 3533, Fax: (65) 6456 3353

Website: www.LexBuild.com, Email: operations@LexBuild.com

ROC / CR GST Reg. No 201736397R

bizSAFE₃