

ASS. REC. BY: TajjREF: CS/TP23005795/TP3**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Wei Hao Vehicle: IN / OUTVeh No: S96296L Yr Regn: 2021, JanType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MAN A95 C.C. 10518Colour: Green A/C: Insured / Std / NI / NASp. Reading: 142794 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WM1A95E26LF014532Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NI / S/Rim / STD A/Rim orTyre Size: F: 275/70R22.5R: 1 ^ (D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 8 mmL/Bal. 8 mm

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt N/S Rooftop
The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. 8/8 mmL/Bal. 8/8 mmD.O.I. 8/6/23Loyang Bus DepotFrt N/S Rooftop

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Rep. Format: _____

Lump Sum / L.B. (\$) _____

Date : 06th June 2023

Quotation No.: Q23-OPS-0902

Go Ahead Singapore Pte Ltd
 2 Loyang Way Singapore 508776
 Tel: 6812 6458

Dear Mr Tan Tuan Boon, Donald Wong

Quotation: Claims Accident repair job for SG6296L - TPC

We are pleased to submit herein, our quotation for your consideration.

S/N	Description	UOM	Total Price
1	Supply skilled labour to replace • Front upper deck windscreen • Front LH tree guard <i>4600/day</i> <i>4300 sealant w/s</i>	1 Job (3 days)	\$ 2,000.00 <i>1500</i>
2	Supply skilled painter & paint material to putty, grinding & spraypaint • Front LH top dome	1 Job (1 day)	\$ 1,000.00 <i>800</i>
3	Front upper deck windscreen	1 PC	\$ 4,698.98 <i>QW</i>
4	Front LH tree guard	1 PC	\$ 757.90 <i>16</i>
Sub - Total			\$ 8,456.88

Terms and Conditions:

Payment Terms : 30 days upon invoice
 Quotation Validity : 30 days
 Lead-Time : 4 working days
 Price quoted subject to 8% GST

Yours faithfully

Tien Yong Shun

Tien Yong Shun
 Manager

Tanpin 97495749
WP' 8/6/23 21145
Resurvey new parts
Tanpin e/khant-wm.
03 days

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LexBuild Motors Pte. Ltd.

11 Tuas Bay Close, #04-01/02 WEST STAR, Singapore 636996

Tel: (65) 6456 3533, Fax: (65) 6456 3353

Website: www.LexBuild.com, Email: operations@LexBuild.com

ROC / CR GST Reg. No 201736397R

bizSAFE₃