



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBS 6543L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT WINDSCREEN P/N: 628 671 2210	CRACKED	3,414.50	3,414.50
1	NS CORNER BUMPER P/N: 628 880 0172	CRACKED	1,594.30	1,594.30
1	NS LAMP BLINKER P/N: 001 820 9121	CUT	130.80	130.80
1	NS HEADLAMP P/N: 002 820 5061	CRACKED	1,100.40	1,100.40
1	WIPER PANEL P/N: 628687040700	CRACKED	765.60	765.60
	LESS 10% DISCOUNT		-	-700.56
			7,005.60	6,305.04
LABOUR				
	REPAIR NS FRONT SIDE COVER.		80.00	80.00
	REMOVAL AND INSTALLATION OF DAMAGE PARTS.		1,100.00	800.00
	BOSTIK SIMSON ISR70-05 ADHESIVE 6 TUBES.		216.00	216.00
	BOSTIK SIMSON PRIMER G PLUS (ADS-9000GP) 0.5 BOTTLE.		45.00	45.00
	PAINTING OF ALL AFFECTED PARTS.		800.00	600.00
			2,241.00	1,741.00
GRAND TOTAL			9,246.60	8,046.04
RECOMMENDED COST OF REPAIRS				8,046.04

Report Ref No. CS/SMR23005812/Tnp3m4

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.