

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMZ 988J

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED	3,215.70	1,184.00
1	REAR BUMPER RETAINER LH	CRACKED	379.35	98.00
1	REAR BUMPER CENTRE BRACKET	CRACKED	573.75	129.00
1	TAILLAMP LH	CRACKED	2,675.70	759.00
1	REVERSE SENSOR	SHORTED	742.50	225.00
1	REAR BUMPER REFLECTOR LH	CRACKED	438.75	78.00
1	REAR FENDER LH	NOT NECESSARY	1,757.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	1,080.00	-
1	REAR END PANEL GARNISH	NOT NECESSARY	249.00	-
6	REVERSE SENSOR RING	NECESSARY	238.00	120.00
	LESS 5% DISCOUNT		-567.49	-
	LESS 10% DISCOUNT		-	-259.30
			10,782.26	2,333.70
	SPECIAL NETT ITEMS			
1	REAR BUMPER CLIPS (SN)	NECESSARY	120.00	30.00
1	TAILLAMP CLIPS (SN)	NOT NECESSARY	100.00	-
1	TAILLAMP SEAL (SN)	NOT NECESSARY	100.00	-
			320.00	30.00
	<u>LABOUR</u>			
	REFIX, REMOVE, REPLACE, REPAIR AFFECTED PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		1,200.00	400.00
	REFIX, REMOVE REVERSE SENSOR.		150.00	30.00
	SPRAY PAINTING.		1,000.00	400.00
			2,350.00	830.00
	GRAND TOTAL		13,452.26	3,193.70



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	2,550.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS3/INC22007815/Svp3m4-1

1/

S MOHAMED IRFAN BIN MOHAMED IQUBAL

Asst. Automotive Assessor

P

ANG BRYAN TANI

Automotive Assessor / Investigator