ALLIED AUTO APPRAISAL

22 Upper Serangoon Crescent #16-53 Singapore 534025

Company Registration No. 53127785B

Our Ref: Allied/TP/22-08037 Veh No : SMZ 988 J Date Report 13-Mar-23 Repairer D'S Graffiti Concepts Pte Ltd Date of Accident 13-Aug-22 Address of Inspection Date of Survey 15-Aug-22

50 Serangoon North Avenue 4,

#02-19, First Centre, Singapore 555856

VEHICLE PARTICULARS & CONDITION

Make & Model : **BMW 316I 1.6 AT 4DR HID** Date of Registration 26-Mar-14 Engine No A676J611N13B16A Engine c.c. 1598 cc : Chassis No WBA3A16030NS36620 COE Expiry Date 25-Mar-24

CONDITION OF VEHICLE

General Condition Good Modification No Air-Conditioner Steering Serviceable Yes Handbrake Serviceable Serviceable Footbrake Wing Mirror Yes Paint Work Good

CONDITION OF TYRES (The below values represent the remaining tyre treads depth)


Front Tyre Size 235/40R18 Rear Tyre Size 235/40R18 Front Left Side 6mm Tourador Rear Left Side Tourador 6mm Front Right Side 6mm Tourador Rear Right Side 6mm Tourador

GENERAL DESCRIPTION OF DAMAGE

The inspected vehicle sustained damage at the **REAR LEFT SIDE** portion.

During visual inspection, our surveyor noted that the rear bumper, left taillamp, rear end panel, rear left fender and among other parts were affected.

All stated damage is subject to consistency of the accident reports.



Repairer Estimate **Our Recommendation**

Parts 10,782.26 Parts: 6,878.00 Nett Item 320.00 Nett Item: 260.00 Labour 2,350.00 Labour: 1,900.00 Total

13,452.26 GST (7.00%):

Total: 9,038.00 Less 20%: 1,807.60 7,230.40

Lump Sum (Estimated): 7,200.00

The repairer agree to repair the vehicle on a Lump Sum Basis with our recommendation of SGD 7,200.00 (SGD Seven Thousand And Two Hundred only) and we are in the opinion the repairer would need about a 5.0 working day period to repair the vehicle.

Allied Auto Appraisal Surveyed by Ng Heng Chai Licensed Appraiser

ALLIED AUTO APPRAISAL

RECOMMENDED PARTS					
No.	Descriptions	Condition	Qty	Repairer	Adjusted
1	REAR BUMPER	Deformed	1	3,215.70	2,382.00 <mark>1</mark> 184 ✓
2	REAR BUMPER RETAINER LH	Cracked	1	379.35	281.00 98 🗸
3	REAR BUMPER CENTRE BRACKET	Cracked	1	573.75	425.00 129 🗸
4	TAILLAMP LH	Cracked	1	2,675.70	1,982.00 ★ nn
5	REVERSE SENSOR	Shorted	1	742.50	550.00 X nn
6	REAR BUMPER REFLECTOR LH	Cracked	1	438.75	325.00 78 🗸
7	REAR FENDER LH	Repair	1	1,757.00	- ×nn
8	REAR END PANEL	Dent	1	1,080.00	975.00 🗙 R
9	REAR END PANEL GARNISH	Necessary	1	249.00	- X nn
10	REVERSE SENSOR RING (6 PCS)	Necessary	1	238.00	320.00 120 🗸
		Sub Total (S\$)	:	11,349.75	7,240.00 1609
		Discount (5%)	: _	567.49	362.00 -5%
		Total Parts (S\$) :	: _	10,782.26	6,878.00 1528.55
RECOMMENDED SPECIAL NETT ITEMS					
No.	Descriptions	Condition		Repairer	Adjusted
1	REAR BUMPER CLIPS	Necessary	1	120.00	100.00 30
2	TAILLAMP CLIPS	Necessary	1	100.00	80.00 X nn
3	TAILLAMP SEAL	Necessary	1	100.00	80.00 × nn
			_	320.00	260.00 30
RECOMMENDED LABOUR					
No.				Repairer	Adjusted
1	REFIX, REMOVE, REPLACE, REPAIR AFFECTED PARTS.	1		1,200.00	1,000.00 400
2	REFIX, REMOVE REVERSE SENSOR.			150.00	100.00 30
3	SPRAY PAINTING.		_	1,000.00	800.00 400
				2,350.00	1,900.00
COST	DF CLAIMS			Repairer	Adjusted 830
1	TOTAL PARTS			10,782.26	6,878.00
2	TOTAL NETT ITEMS			320.00	260.00
3	LABOUR & SPRAY			2,350.00	1,900.00
		Gross Total (S\$) :	: -	13,452.26	9,038.00
		GST 7.00% (S\$):			
		Total Amount (S\$) :	: [13,452.26	9,038.00
			-		

2388.55

L/S - 1910.84 = 1900

4 days