

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EQI23005828/TQY3M4**Date:** 20/06/2023**REFERENCE**

Handling Insurer: EQ Insurance Company Ltd Policy No:

Claimant Vehicle No : SHA4296L **Insured Vehicle No :** SNH7094A

Date of Loss: 06/06/2023 Nature of Claim: TP Claim No: DM23HO01219

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHA4296L**

Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) Engine No: 2ZR2C18243

Reg. Date: 15/05/2019 (Man. Year: 2018) Chassis No: JTDKB3FU503080649

Colour: Blue Odometer: 370293 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15

Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm

Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,137.81	0.00	1,137.81	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,140.00	880.00	260.00	22.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,277.81	880.00	1,397.81	61.37
+ GST 8.00/8.00% (S\$)	182.22	70.40	111.82	61.37
Nett Amount (S\$)	2,460.03	950.40	1,509.63	61.37

INSPECTION

Date of Assignment: 08/06/2023 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)
COMFORTDELGRO ENGINEERING PTE LTD

Date Inspected: 09/06/2023 Inspected At: 59 LOYANG DRIVE
SINGAPORE 508969

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Jun 2023)
Parts:	144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA4296L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	503.04 FL	*- FL
2	1		*REAR BUMPER CLIPS	Not Necessary	22.00 FL	*- FL
3	1		*REAR FENDER RH	Repair	992.04 FL	*- FL
F=Franchise part. L=ListItemDisc.						
Sub Total (S\$)					1,517.08	0.00
- List Item Discount on L Items 25.00/25.00% (S\$)					379.27	0.00
Total Parts (S\$)					1,137.81	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	400.00	350.00
2	SPRAY PAINTING CHARGE	New	600.00	500.00
3	REMOVE/ REFIX REVERSE SENSOR	New	60.00	30.00
4	TUFF KOTE	New	80.00	0.00
Gross Labour Cost (\$\$)			1,140.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >