

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01 (Claims & Performance Management)
Singapore 068897

Our File No: CC3/AIS23005838/RNP3E2**Date:** 20/07/2023**REFERENCE**

Insured/Claimant:	ZHANG CHUDI	Policy No:	SP2003304297	
Date of Loss:	06/06/2023	Nature of Claim:	OD	Claim No: 202332009169

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNH6663P		
Make & Model:	VOLKSWAGEN ARTEON, 2.0 R-LINE (A)	Engine No:	DNN107582
Reg. Date:	11/11/2022 (Man. Year: 2022)	Chassis No:	WVWZZZ3HZPE001536
Colour:	Grey	Odometer:	8719 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$263,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/35 R20	Rear Tyre Size:	245/35 R20
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	30,580.03	21,498.03	9,082.00	29.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	19,750.00	14,560.00	5,190.00	26.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	50,330.03	36,058.03	14,272.00	28.36
- Excess (\$\$)	750.00	750.00	0.00	0.00
(\$\$)	49,580.03	35,308.03	14,272.00	28.79
+ GST 8.00/8.00% (\$\$)	3,966.40	2,824.64	1,141.76	28.79
Nett Amount (\$\$)	53,546.43	38,132.67	15,413.76	28.79

INSPECTION

Date of Assignment:	08/06/2023	
Date Inspected:	09/06/2023	Inspected At: Volkswagen Group Singapore Pte Ltd (tuas) (HQ) 17 Tuas Ave 9 Singapore 639197
Estimated Period of Repair:	25.0 days	

Adjuster: MOHD RASUL**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Jul 2023)
Parts:	143	VOLKSWAGEN ARTEON 2.0 R-LINE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNH6663P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*WATER DEFLECTOR BLACK FRT W/SCREEN SIDE MLDG RH	Scratched	38.01 FS	*38.01 FS
2	1		*HOOD FRT BONNET	Repair	2,338.64 FS	*- FS
3	1		*FENDER RH	Bent	661.00 FS	*661.00 FS
4	1		*RIVET (6PCS)	Necessary	5.49 FS	*5.49 FS
5	1		*WHEELHOUSE LINER RHS FENDER LINER (UPPER)	Not Necessary	173.90 FS	*- FS
6	1		*END PLATE RHS FENDER ELEMENT	Necessary	69.43 FS	*69.43 FS
7	1		*COVER PRIMED RHS FENDER LOWER GARNISH	Not Necessary	129.46 FS	*- FS
8	1		*EMBLEM RHS FENDER EMBLEM	Cracked	62.44 FS	*62.44 FS
9	1		*REAR VIEW MIRROR HOUSING	Cracked	1,292.26 FS	*1,292.26 FS
10	1		*MIRROR GLASS	Chipped	568.65 FS	*568.65 FS
11	1		*MIRROR CAP PRIMED	Melted	128.08 FS	*128.08 FS
12	1		*WARNING DISPLAY FOR LANE	Scratched	99.42 FS	*99.42 FS
13	1		*DOOR RHS FRT DOOR	Torn	2,484.82 FS	*2,484.82 FS
14	1		*DOOR SEAL OUTER BLACK	Necessary	158.47 FS	*158.47 FS
15	1		*ALU-LAMIN.INSULATION DOOR INSULATION	Necessary	31.44 FS	*31.44 FS
16	2		*BOLT WITH POLYGON SOCKET	Necessary	8.22 FS	*8.22 FS
17	1		*DOOR HINGE RHS FRT DOOR LOWER HINGE	Not Necessary	124.06 FS	*- FS
18	1		*DOOR LATCH RHS FRT DOOR LOCK	Not Necessary	233.07 FS	*- FS
19	1		*FILL.HD. SCREW (2PCS)	Necessary	4.49 FS	*4.49 FS
20	1		*EXPANDING NUT (2PCS)	Necessary	2.97 FS	*2.97 FS
21	1		*WINDOW REGULATOR WITHOUT	Not Necessary	405.87 FS	*- FS
22	1		*CLIP (6PCS)	Necessary	7.65 FS	*7.65 FS
23	1		*CLIP-LOWER PART	Necessary	1.30 FS	*1.30 FS
24	1		*COVER FOR DOOR PRIMED RHS FRT DOOR LOWER PROTECTOR	Scratched	111.05 FS	*111.05 FS
25	1		*DECORATIVE MOULDING CHROM RHF DOOR LOWER PROTECTOR MLDG CHROM	Scratched	152.04 FS	*152.04 FS
26	1		*CLIP (7PCS)	Necessary	2.82 FS	*2.82 FS
27	1		*GROMMET (7PCS)	Necessary	9.48 FS	*9.48 FS
28	1		*EMBLEM RHF DOOR EMBLEM	Necessary	62.44 FS	*62.44 FS
29	1		*WATER DEFLECTOR ALUMINIUM A-B PILLAR TOP MLDG CHROM	Cut	333.04 FS	*333.04 FS
30	1		*POP-RIVET (13PCS)	Necessary	10.67 FS	*10.67 FS
31	1		*POP-RIVET (6PCS)	Necessary	2.64 FS	*2.64 FS
32	1		*DOOR RHS REAR DOOR	Bent	2,484.82 FS	*2,484.82 FS
33	1		*DOOR SEAL OUTER BLACK	Necessary	162.50 FS	*162.50 FS
34	1		*ALU-LAMIN. INSULATION DOOR INSULATION	Necessary	31.44 FS	*31.44 FS
35	2		*BOLT WITH POLYGON SOCKET	Necessary	8.22 FS	*8.22 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*FILL.HD.SCREW (2PCS)	Necessary	4.49 FS	*4.49 FS
37	6		*POP-RIVET	Necessary	2.64 FS	*2.64 FS
38	1		*CLIP (6PCS)	Necessary	7.65 FS	*7.65 FS
39	1		*CLIP-LOWER PART	Necessary	1.30 FS	*1.30 FS
40	1		*COVER FOR DOOR PRIMED RHR DOOR LOWER PROTECTOR	Scratched	522.02 FS	*522.02 FS
41	1		*DECORATIVE MOULDING CHROM RHR DOOR LOWER PROTECTOR MLDG CHROM	Necessary	113.88 FS	*113.88 FS
42	1		*CLIP (5PCS)	Necessary	2.02 FS	*2.02 FS
43	1		*GROMMET (5PCS)	Necessary	6.77 FS	*6.77 FS
44	1		*PROTECTIVE FOIL RHS ROCKER PANEL FOIL	Necessary	13.42 FS	*13.42 FS
45	1		*CLIP (8PCS)	Necessary	3.23 FS	*3.23 FS
46	1		*SECTIONAL PART SIDE PANEL RHS REAR FENDER	Bent	2,262.69 FS	*2,262.69 FS
47	1		*RIVETTED CAP NUT (3PCS)	Necessary	3.89 FS	*3.89 FS
48	1		*WHEELHOUSE PROTECTOR RHS REAR FENDER LINER	Not Necessary	198.94 FS	*- FS
49	1		*EXPANDING NUT (8PCS)	Necessary	11.87 FS	*11.87 FS
50	1		*2K-INSERT FOAM	Necessary	127.21 FS	*127.21 FS
51	1		*SEALANT CAN BE SPRAYED	Necessary	52.88 FS	*52.88 FS
52	1		*ZINC SPRAY	Necessary	54.58 FS	*54.58 FS
53	1		*2K-BODY ADHESIVE	Necessary	366.65 FS	*366.65 FS
54	1		*VENT TRIM RHS REAR FENDER AIR DUCT	Not Necessary	50.21 FS	*- FS
55	1		*SIDE WINDOW NOT PRE-TREAT RHS REAR FENDER GLASS	Necessary	377.35 FS	*377.35 FS
56	1		*1K WINDOW ADHESIVE	Necessary	36.53 FS	*36.53 FS
57	1		*ALL PURPOSE CLEANER	Necessary	60.96 FS	*60.96 FS
58	1		*PRIMER	Necessary	17.94 FS	*17.94 FS
59	1		*APPLICATOR (2PCS)	Necessary	13.23 FS	*13.23 FS
60	1		*ACTIVATOR	Necessary	15.57 FS	*15.57 FS
61	1		*COVER PRIMED REAR BUMPER	Deformed	1,430.76 FS	*1,430.76 FS
62	1		*SENSOR BRACKET	Necessary	10.14 FS	*10.14 FS
63	1		*SENSOR BRACKET	Necessary	10.14 FS	*10.14 FS
64	1		*SENSOR BRACKET	Necessary	10.14 FS	*10.14 FS
65	2		*SENSOR BRACKET	Necessary	20.28 FS	*20.28 FS
66	1		*SENSOR BRACKET	Necessary	10.14 FS	*10.14 FS
67	1		*SENSOR PRIMED (2PCS)	Not Working	280.27 FS	*280.27 FS
68	2		*SEAL RING SATIN BLACK	Necessary	2.20 FS	*2.20 FS
69	1		*POP-RIVET (10PCS)	Necessary	9.79 FS	*9.79 FS
70	1		*BUMPER REAR BUMPER REINFORCEMENT	Not Necessary	710.45 FS	*- FS
71	1		*ATTACHMENT STRIP BUMPER CTR BRACKET	Not Necessary	66.48 FS	*- FS
72	1		*GUIDE LHR BUMPER BRACKET (UPPER)	Not Necessary	28.06 FS	*- FS
73	1		*GUIDE RHR BUMPER BRACKET (UPPER)	Cracked	28.06 FS	*28.06 FS
74	1		*GUIDE PIECE LHR BUMPER BRACKET (SIDE)	Not Necessary	74.56 FS	*- FS
75	1		*GUIDE PIECE RHR BUMPER BRACKET (SIDE)	Cracked	74.56 FS	*74.56 FS
76	1		*DECORATIVE MOULDING BRIGH RHS BUMPER LOWER MLDG CHROM	Not Necessary	136.98 FS	*- FS
77	1		*REFLECTOR RHS REFLECTOR INNER	Cracked	62.30 FS	*62.30 FS
78	1		*REFLECTOR RHS REFLECTOR OUTER	Cracked	62.30 FS	*62.30 FS
79	1		*LED TAIL LIGHT RHS TAILLIGHT OUTER	Not Necessary	667.86 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
80	1		*LED TAIL LIGHT RHS TAILLIGHT INNER	Not Necessary	503.18 FS	*- FS
81	2		*MOUNTING TAILLIGHT OUTER BUSH	Necessary	0.84 FS	*0.84 FS
82	1		*REAR TRUNK LID	Bent	2,583.96 FS	*2,583.96 FS
83	1		*1K WINDOW ADHESIVE (2PCS)	Necessary	73.05 FS	*73.05 FS
84	1		*PRIMER	Necessary	17.94 FS	*17.94 FS
85	1		*ACTIVATOR	Necessary	15.57 FS	*15.57 FS
86	1		*APPLICATOR (2PCS)	Necessary	13.23 FS	*13.23 FS
87	1		*SPOILER BLACK BOOT LID TOP SPOILER	Necessary	1,012.56 FS	*1,012.56 FS
88	1		*PRIMER	Necessary	27.61 FS	*27.61 FS
89	1		*1K WINDOW ADHESIVE	Necessary	28.07 FS	*28.07 FS
90	1		*HOOD LATCH BOOT LID LOCK	Not Necessary	150.37 FS	*- FS
91	1		*GASKET BOOT LID TOP SEAL	Not Necessary	109.71 FS	*- FS
92	1		*INSCRIPTION BRIGHT CHROME NAME PLATE - ARTEON	Necessary	67.92 FS	*67.92 FS
93	1		*HIGH-MOUNTED BRAKE LIGHT 3RD BRAKELIGHT	Necessary	345.52 FS	*345.52 FS
94	1		*SET GASKET	Not Necessary	39.84 FS	*- FS
95	1		*CONTROL UNIT FOR BLIND SP RHS BLIND SPOT CONTROL UNIT	Not Necessary	743.92 FS	*- FS
96	1		*BRACKET FOR ELEC.CONTR.M BLIND SPOT CONTROL UNIT BRACKET RH	Cracked	7.70 FS	*7.70 FS
97	1		*ALLOY WHEEL DARK GRAPHITE RHS FRT RIM	Scratched	2,036.04 FS	*2,036.04 FS
98	1		*RUBBER VALVE	Necessary	2.87 FS	*2.87 FS
99	1		*ALLOY WHEEL DARK GRAPHITE RHS REAR RIM	Not Necessary	2,036.04 FS	*- FS
100	1		*RUBBER VALVE	Not Necessary	2.87 FS	*- FS
101	1		*ROOF FRAME SEAL	Not Necessary	104.47 FS	*- FS
102	1		*REAR FENDER GLASS SOLAR FILM	Necessary	180.00 FS	*180.00 FS
103	1		*COVER FENDER TOP COVER RH	Not Necessary	53.06 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **30,580.03** **21,498.03**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR	New	200.00	200.00
2	B&P DIAGNOSIS AND PROGRAMMING	New	360.00	360.00
3	TO ALIGN HEADLIGHT	New	100.00	100.00
4	R&R ROOFLINING	New	1,680.00	840.00
5	360 CAMERA CALIBRATION	New	560.00	560.00
6	CHANGE LANE ASSIST SYSTEM CALIBRATION	New	560.00	560.00
7	B&P WHEEL ALIGNMENT	New	300.00	300.00
8	R&R RIM & BALANCE	New	100.00	50.00
9	LABOUR	New	5,600.00	4,480.00
10	SPRAY PAINT	New	6,360.00	4,770.00
11	TRANSFER DOOR MECHANISM	New	1,060.00	560.00
12	R&R REAR LUGGAGE TRIM	New	530.00	280.00
13	R&R REAR SEAT	New	560.00	280.00
14	R&R REAR W/SCREEN	New	560.00	560.00
15	TRANSFER REAR BOOT LID MECHANISM	New	560.00	280.00
16	R&R REAR FENDER GLASS	New	560.00	280.00
17	REAR WATER LEAK TEST	New	100.00	100.00
Gross Labour Cost (S\$)			19,750.00	14,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >