

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/ICS23005912/RNY3M4**Date:** 27/06/2023REFERENCE

Handling Insurer: ECICS Limited Policy No: MPC23P00076200
Claimant Vehicle No : XE5533K **Insured Vehicle No :** SLW3328Y
 Date of Loss: 01/06/2023 Nature of Claim: TP Claim No: DMPC2300447H /AF

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **XE5533K**
 Make & Model: MITSUBISHI FV51JJD4RDEA, 12.9 D (M) Engine No: 6M70428627
 Reg. Date: 19/12/2008 (Man. Year: 2008) Chassis No: FV51JJA00407
 Colour: White Odometer: 918133 km
 Engine Capacity: 12882 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 12R22.5 Rear Tyre Size: 12R22.5 (D/D)
 Front Left Side: Inning 8 mm Rear Left Side: Inning 8/8 mm
 Front Right Side: Inning 8 mm Rear Right Side: Inning 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 09/06/2023
 Date Inspected: 12/06/2023 Inspected At: Carport Auto Service (HQ)
 Block 3, Pioneer Road North, #01-24
 Singapore 628457
 Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF
\$4,000.00-\$5,000.00

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 27 Jun 2023)	
Parts:	N/A	MITSUBISHI FV51JJD4RDEA 12.9 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XE5533K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >