

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 4525B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR FENDER RH	TO REPAIR SEE LABOUR	992.04	-
1	REAR DOOR PANEL RH	BENT	1,258.30	1,258.30
1	ROCKER SIDE PANEL GARNISH RH	TO REPAIR SEE LABOUR	576.00	-
	LESS 25% DISCOUNT		-706.59	-314.58
			2,119.75	943.72
	NETT ITEMS			
1	FRONT DOOR COMFORT LOGO STICKER (N)	NOT NECESSARY	75.00	-
1	REAR DOOR COMFORT APP STICKER (N)	NECESSARY	80.00	80.00
	LESS 10% DISCOUNT		-15.50	-8.00
			139.50	72.00
	SPECIAL NETT ITEMS			
1	REAR FENDER ADVERTISEMENT (SN)	CUT	100.00	100.00
1	FRONT DOOR ADVERTISEMENT (SN)	NOT NECESSARY	100.00	-
1	REAR DOOR ADVERTISEMENT (SN)	CUT	100.00	100.00
			300.00	200.00
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR FENDER RH AND ROCKER SIDE PANEL GARNISH RH.		750.00	525.00
	SPRAY PAINTING CHARGE.		800.00	600.00
	REMOVE/REFIX DOOR PARTS.		90.00	60.00
	REMOVE/REFIX REAR UPHOLSTERY.	NOT NECESSARY	90.00	
			1,730.00	1,185.00
	GRAND TOTAL		4,289.25	2,400.72





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,900.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. NS/INC23005930/Tqp3m4

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser