

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/HLA23005934/KNY3M4
Date: 19/06/2023

REFERENCE

Handling Insurer: HL Assurance Pte Ltd Policy No: MP319773
Claimant Vehicle No : SHB7932J **Insured Vehicle No :** SCQ1681C
 Date of Loss: 09/06/2023 Nature of Claim: TP Claim No: MPC04308

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHB7932J**
 Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) Engine No: 2ZR2C13088
 Reg. Date: 24/05/2019 (Man. Year: 2018) Chassis No: JTDKB3FU103080292
 Colour: Metallic Pearl White/Red Odometer: 426944 km
 Engine Capacity: 1798 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
 Front Left Side: Wanli 7 mm Rear Left Side: Wanli 6 mm
 Front Right Side: Wanli 7 mm Rear Right Side: Wanli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,187.44	1,604.53	4,582.91	74.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,570.00	870.00	3,700.00	80.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,757.44	2,474.53	8,282.91	77.00
Approved Total (Overridden) (S\$)		2,000.00		
(S\$)	10,757.44	2,000.00	8,757.44	81.41
+ GST 8.00/8.00% (S\$)	860.60	160.00	700.60	81.41
Nett Amount (S\$)	11,618.04	2,160.00	9,458.04	81.41

INSPECTION

Date of Assignment: 09/06/2023
 Date Inspected: 12/06/2023 Inspected At: TRANS-CAB AUTO SERVICES PTE LTD
 SINGAPORE 569111
 Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Jun 2023)
Parts:	144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB7932J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER, FRONT BUMPER	Buckled/Dented	653.31 FL	*653.31 FL
2	1		*ABSORBER, FRONT BUMPER ENERGY	Serviceable	100.17 FL	*- FL
3	1		*REINFORCEMENT SUB-ASSY, FRONT BUMPER	Repair	902.16 FL	*- FL
4	1		*SUPPORT, FRONT BUMPER SIDE, LH	Distorted	100.49 FL	*100.49 FL
5	1		*STAY SUB-ASSY, FRONT BUMPER, LH	Serviceable	59.85 FL	*- FL
6	1		*LINER, FRONT FENDER, LH	Serviceable	255.36 FL	*- FL
7	1		*FENDER SUB-ASSY, FRONT LH	Bent	1,236.69 FL	*1,236.69 FL
8	1		*FRONT FENDER EMBLEM LH	Necessary	68.88 FL	*68.88 FL
9	1		*LAMP ASSY, FOG, LH	Serviceable	1,200.78 FL	*- FL
10	1		*UNIT ASSY, HEADLAMP, LH	Serviceable	3,325.56 FL	*- FL
11	1		*FENDER LINER CLIP	Not Necessary	65.00 FS	*- FS
12	1		*FRT BUMPER CLIP	Necessary	65.00 FS	*60.00 FS
13	1		*FRT LH BUMPER BRACKET CLIP	Not Necessary	65.00 FS	*- FS
14	1		*FENDER LINER CLIP	Not Necessary	65.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,163.25	2,119.37
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,975.81	514.84
Total Parts (\$\$)	6,187.44	1,604.53

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST-PROOFING OF THE AFFECTED AREAS	New	600.00	30.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,200.00	440.00
3	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	2,000.00	400.00
4	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTNGS AND OTHER, TO ENABLE REPAIR	New	380.00	0.00
5	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
6	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
Gross Labour Cost (S\$)			4,570.00	870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >