

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG23005963/AVY3M4**Date:** 27/07/2023REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001774063
Claimant Vehicle No :	SNJ7394Z	Insured Vehicle No :	SNA3419K
Date of Loss:	03/06/2023	Nature of Claim:	TP
		Claim No:	316754

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNJ7394Z	Engine No:	LEB7609994
Make & Model:	HONDA SHUTTLE HYBRID, 1.5 (A)	Chassis No:	GP72208090
Reg. Date:	23/02/2023 (Man. Year: 2021)	Odometer:	21704 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,449.62	1,358.54	3,091.08	69.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,770.00	1,140.00	1,630.00	58.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,219.62	2,498.54	4,721.08	65.39
Approved Total (Overridden) (S\$)		2,000.00		
(S\$)	7,219.62	2,000.00	5,219.62	72.30
+ GST 8.00/8.00% (S\$)	577.57	160.00	417.57	72.30
Nett Amount (S\$)	7,797.19	2,160.00	5,637.19	72.30

INSPECTION

Date of Assignment:	14/06/2023	Teamwork Garage Pte Ltd (HQ)
Date Inspected:	13/06/2023	Inspected At: 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park
Estimated Period of Repair:	4.0 days	Singapore 408934

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 26 Jul 2023)	
Parts:	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNJ7394Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR RH	Dented	841.72 FL	*841.72 FL
2	1		*REAR DOOR TAPE RH	Necessary	81.60 FL	*81.60 FL
3	1		*REAR DOOR LOCK RH	Not Necessary	461.30 FL	*- FL
4	1		*REAR DOOR REGULATOR MOTOR RH	Damaged	302.30 FL	*302.30 FL
5	1		*REAR DOOR INNER TRIM BOARD RH	Not Necessary	829.40 FL	*- FL
6	1		*REAR FENDER RH	Repair	1,066.67 FL	*- FL
7	1		*REAR FENDER INNER SHIELD RH	Not Necessary	189.20 FL	*- FL
8	1		*SIDE SKIRT RH	Deformed	435.05 FL	*435.05 FL
9	1		*REAR WHEEL HUB W BEARING RH	Not Necessary	325.38 FL	*- FL
10	1		*REAR SHOCK ABSORBER RH	Not Necessary	279.40 FL	*- FL
11	1		*SET REAR DOOR INNER TRIM BOARD CLIP	Not Necessary	50.00 FS	*- FS
12	1		*SET REAR FENDER INNER SHIELD CLIP	Not Necessary	50.00 FS	*- FS
13	1		*SET SIDE SKIRT CLIP	Necessary	50.00 FS	*30.00 FS
14	1		*REAR RIM RH	Not Necessary	450.00 FS	*- FS
					Sub Total (S\$)	5,412.02 1,690.67
					- List Item Discount on L Items 20.00/20.00% (S\$)	962.40 332.13
					Total Parts (S\$)	4,449.62 1,358.54

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING AND LIGHTINGS SYSTEM	New	120.00	30.00
2	COMPUTERIZE AND CHECK WHEEL ALIGNMENT	New	200.00	0.00
3	REMOVE & REPLACE REAR UNDERCARRIAGE	New	150.00	0.00
4	REMOVE & REFIT REAR DOOR TRIMS & GARNISHES	New	150.00	60.00
5	PANEL BEATING ON AFFECTED AREAS	New	1,000.00	400.00
6	SPRAY PAINTING ON AFFECTED AREAS	New	1,000.00	600.00
7	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	50.00
Gross Labour Cost (\$\$)			2,770.00	1,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >