



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909			Ref: CS/UOI23005968/Kny3m4 Date: 06/07/2023 Code: UOI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMF 5387R	Veh. Inspected	GBD 2911M
	Policy No.		Coverage (\$)	0.00
	Claim No.	M12D00182306	Excess (\$)	0.00
	Assign From	JOANNE YONG	Assign Date	12/06/2023
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HIACE (A)	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	KDH2010143803	Colour	METALLIC BLACK
	Odometer	269904 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195R 15X8	SAILUN	9 mm
	L/H Front Tyre	195R 15X8	SAILUN	9 mm
	R/H Rear Tyre	195R 15X8	SAILUN	9 mm
	L/H Rear Tyre	195R 15X8	SAILUN	9 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	05/06/2023	Inspection Date	13/06/2023
	Survey held at	MADLANE AUTO PTE LTD 60 JALAN LAM HUAT #02-18/19 CARROS CENTRE SINGAPORE 737869		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	