

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS23005972/TVY3Q2**Date:** 26/06/2023**REFERENCE**

Handling Insurer: ECICS Limited Policy No:

Claimant Vehicle No : SHA9228B **Insured Vehicle No :** GBF4684U

Date of Loss: 08/06/2023 Nature of Claim: TP Claim No: DMCV2300037H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHA9228B**

Make & Model: HYUNDAI I40, 1.7 D (A) Engine No: HIDDEN

Reg. Date: 07/04/2016 (Man. Year: 2016) Chassis No: KMHLB41UMGU085887

Colour: Yellow Odometer: 891873 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16

Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm

Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,589.40	1,479.00	1,110.40	42.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,800.00	1,305.00	495.00	27.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,389.40	2,784.00	1,605.40	36.57
Approved Total (Overridden) (S\$)		2,250.00		
(S\$)	4,389.40	2,250.00	2,139.40	48.74
+ GST 8.00/8.00% (S\$)	351.15	180.00	171.15	48.74
Nett Amount (S\$)	4,740.55	2,430.00	2,310.55	48.74

INSPECTION

Date of Assignment: 12/06/2023

Date Inspected: 12/06/2023 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Jun 2023)
Parts:	143	HYUNDAI I40 1.7 D (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA9228B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	10		*HEADLAMP LH	Not Necessary	1,388.00 FL	*- FL
2	1		*FRT FENDER LH	Bent	663.00 FL	*663.00 FL
3	1		*FRT BUMPER ASSY	Deformed	1,025.20 FL	*1,025.20 FL
4	1		*FRT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
5	1		*FRT BUMPER SIDE BRACKET LH	Deformed	44.80 FL	*44.80 FL
6	1		*FRT DOOR COMFORT LOGO	Necessary	75.00 FS	*75.00 FS
					Sub Total (\$\$)	3,218.00 1,830.00
					- List Item Discount on L Items 20.00/20.00% (\$\$)	628.60 351.00
					Total Parts (\$\$)	2,589.40 1,479.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	900.00	525.00
2	SPRAY PAINT	New	800.00	750.00
3	TUFF KOTE	New	50.00	30.00
4	CHECK WIRING	New	50.00	0.00
Gross Labour Cost (\$\$)			1,800.00	1,305.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >