



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 6649Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT BUMPER	DEFORMED	586.18	586.18
10	FRT BUMPER CLIPS	NECESSARY	22.00	22.00
1	FRT FENDER LH	BENT	1,111.93	1,111.93
1	FRT FENDER EMBLEM LH	NECESSARY	86.50	86.50
1	HEADLAMP ASSY LH	CRACKED	2,637.60	2,637.60
1	FRT SIDE MIRROR ASSY	BROKEN	1,390.10	1,390.10
1	FRT SIDE MIRROR COVER	DISTORTED	141.90	141.90
1	FRT BUMPER SIDE BRACKET LH	DISTORTED	82.30	82.30
	LESS 25% DISCOUNT		-1,514.63	-1,514.63
			4,543.88	4,543.88
	<u>NETT ITEMS</u>			
1	FRT DOOR COMFORT LOGO (N)	NECESSARY	75.00	75.00
	LESS 10% DISCOUNT		-7.50	-7.50
			67.50	67.50
	<u>LABOUR</u>			
	PANEL BEAT.		800.00	525.00
	SPRAYPAINT.		800.00	750.00
	CHECK WIRING.		50.00	30.00
	TUFF KOTE.		50.00	30.00
			1,700.00	1,335.00
	GRAND TOTAL		6,311.38	5,946.38
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			4,750.00

Report Ref No. NS/INC23005973/Tvp3m4

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.