



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 3250A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRT FENDER RH	TO REPAIR SEE LABOUR	588.80	-
10	FRT FENDER EMBLEM RH	NECESSARY	26.60	26.60
1	FRT SIDE MIRROR RH	CRACKED	1,391.70	1,391.70
	LESS 25% DISCOUNT		-501.78	-354.58
			1,505.32	1,063.72
SPECIAL NETT ITEMS				
1	FRT DOOR COMFORT LOGO (SN)	NECESSARY	80.00	80.00
			80.00	80.00
LABOUR				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRT FENDER RH.		1,100.00	525.00
	SPRAY PAINT.		800.00	700.00
	TUFF KOTE.	NOT NECESSARY	50.00	-
	CHECK WIRING.	NOT NECESSARY	50.00	-
			2,000.00	1,225.00
GRAND TOTAL			3,585.32	2,368.72
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,900.00

Report Ref No. NS/INC23005974/Tvp3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.