



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 8598Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRT BUMPER COVER	DEFORMED	481.10	481.10
10	FRT BUMPER CLIPS	NECESSARY	22.00	22.00
1	FRT BUMPER SIDE BRACKET RH	DEFORMED	28.00	28.00
1	FRT BUMPER MOULDING CENTRE UPPER	CUT	368.50	368.50
1	HEADLAMP RH	NOT NECESSARY	2,110.30	-
1	FRT BUMPER SIDE MOULDING RH	NOT NECESSARY	93.60	-
1	FRT FENDER RH	BENT	588.80	588.80
1	FRT FENDER BLUE-DRIVE EMBLEM RH	NECESSARY	26.60	26.60
1	FRT WHEEL COVER RH	CUT	217.20	217.20
	LESS 20% DISCOUNT		-787.22	-346.44
			3,148.88	1,385.76
LABOUR				
	PANEL BEATING.		750.00	350.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	CHECK ALL LIGHTING.	NOT NECESSARY	60.00	-
			1,410.00	850.00
GRAND TOTAL			4,558.88	2,235.76
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,800.00

Report Ref No. NS/INC23005980/Tvp3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.