



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1396R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER	NECESSARY	459.40	459.40
1	REAR BUMPER SIDE BRACKETS RH	NOT NECESSARY	55.80	-
1	REAR BUMPER CENTRE MOULDING	CRACKED	451.25	451.25
10	REAR BUMPER COVER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	REAR BUMPER REFLECTOR LAMP RH	CUT	41.15	41.15
1	REAR WHEEL CAP RH	CUT	346.40	346.40
	LESS 20% DISCOUNT		-275.20	-264.04
			1,100.80	1,056.16
<b>SPECIAL NETT ITEMS</b>				
1	REAR BUMPER MAT (SN)	NECESSARY	50.00	50.00
			50.00	50.00
<b>LABOUR</b>				
	PANEL BEATING - REAR FENDER ARCH RH ETC.		800.00	525.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	REMOVE / REFIX REVERSE SENSOR.		120.00	30.00
			1,520.00	1,055.00
<b>GRAND TOTAL</b>			<b>2,670.80</b>	<b>2,161.16</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>1,750.00</b>

Report Ref No. NS/INC23005984/Tqp3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.