



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 9499E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	SLIDING DOOR RH	BENT	1,798.00	1,611.00
1	SLIDING DOOR INNER TRIM BOARD	BUCKLED	312.00	312.00
1	SLIDING DOOR LOCK RH	TO REPAIR SEE LABOUR	321.00	-
1	SLIDING DOOR LOWER ROLLER HINGE	TO REPAIR SEE LABOUR	321.00	-
1	SLIDING DOOR RAILING RH	SERVICEABLE	398.20	-
1	SLIDING DOOR FRAME PANEL RH	TO REPAIR SEE LABOUR	687.00	-
1	REAR SIDE BODY PANEL RH	BENT	1,528.00	1,528.00
1	ROCKER PANEL RH	TO REPAIR SEE LABOUR	1,025.00	-
1	REAR WHEEL AXLE	SERVICEABLE	2,890.00	-
1	REAR SHOCK ABSORBER RH	SERVICEABLE	258.00	-
1	REAR WHEEL BEARING RH	SERVICEABLE	198.00	-
	LESS 25% DISCOUNT		-2,434.05	-862.75
			7,302.15	2,588.25
1	SLIDING DOOR WEATHERSTRIP (50%) (SN)	DENTED	259.00	129.50
	LESS 25% DISCOUNT		-64.75	-
			194.25	129.50
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET REAR BUMPER CLIPS RH (SN)	NOT NECESSARY	60.00	-
1	REAR WHEEL HUB RH (SN)	NOT NECESSARY	100.00	-
1	REAR FENDER INNER PANEL SEALANT (SN)	NECESSARY	80.00	30.00
			240.00	30.00
<b><u>LABOUR</u></b>				
	PANEL BEATING AND REPLACE PARTS. INCLUSIVE OF THE REPAIR OF SLIDING DOOR LOCK RH, SLIDING DOOR LOWER ROLLER HINGE, SLIDING DOOR FRAME PANEL RH AND ROCKER PANEL RH.		1,600.00	800.00
	SPRAY PAINTING TO AFFECTED AREA.		1,400.00	650.00

Report Ref No. CS/INC23005990/Kvy3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE AND REFIT SLIDING DOOR MECHANISM.		150.00	60.00
	TUFF COAT.		250.00	60.00
	CONDUCT WHEEL ALIGNMENT.		120.00	60.00
	WIRNING, BULB CHECKING.		80.00	20.00
	REMOVE AND REPLACE REAR UNDERCARRIAGE.	NOT NECESSARY	600.00	-
	CONDUCT FULL WHEEL ALIGNMENT.	REPEATED	120.00	-
			4,320.00	1,650.00
	<b>GRAND TOTAL</b>		<b>12,056.40</b>	<b>4,397.75</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>			<b>3,500.00</b>

Report Ref No. CS/INC23005990/Kvy3e2

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.