



ESTABLISHED 1984

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD
75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557
ATTN: YEE PEI LI

Ref: CS/INC23005990/Kvy3e2
Date: 05/07/2023
Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBH 7110D	Veh. Inspected	GBF 9499E
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1223623-002	Excess (\$)	0.00
Assign From	HAZALYSA	Assign Date	13/06/2023

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HIACE (M)	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTFHT02P300215772	Colour	SILVER
Odometer	161510 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15X8	BRIDGESTONE	9 mm
L/H Front Tyre	195 R15X8	BRIDGESTONE	9 mm
R/H Rear Tyre	195 R15X8	BRIDGESTONE	9 mm
L/H Rear Tyre	195 R15X8	BRIDGESTONE	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	18/05/2023	Inspect Date / Time	13/06/2023 (11:52 AM)
Survey held at	60 JALAN LAM HUAT #02-18/19 CARROS CENTRE		
Repairer	MADLANE AUTO		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**