



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCY 6006C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BOOT LID (N)	TO REPAIR SEE LABOUR	2,200.00	-
1	REAR BOOT RUBBER (N)	NOT NECESSARY	185.00	-
2	REAR BOOT HINGES (N)	NOT NECESSARY	270.00	-
1	REAR BOOT INNER LOCK (N)	NOT NECESSARY	295.00	-
1	REAR BOOT LOGO (N)	NECESSARY	78.00	78.00
2	REAR TAILLAMPS (N)	NOT NECESSARY	1,670.00	-
1	REAR END PANEL (N)	TO REPAIR SEE LABOUR	1,248.00	-
1	REAR END PANEL INNER GARNISH (N)	NOT NECESSARY	165.00	-
1	REAR BUMPER (N)	DISTORTED	2,085.00	1,899.21
2	REAR BUMPER BRACKETS (N)	O/S CRACKED/ N/S NOT NECESSARY (1PC ONLY)	172.00	86.00
1	REAR BUMPER REINFORCEMENT (N)	BENT	817.00	621.22
2	REAR BUMPER SIDE RETAINERS (N)	NOT NECESSARY	170.00	-
1	REAR BUMPER LOWER DIFFUSER (N)	DISTORTED	1,280.00	645.11
2	REAR BUMPER PDC SENSORS (N)	MALFUNCTION	770.00	450.00
2	REAR BUMPER SIDE SENSORS (N)	NOT NECESSARY	770.00	-
1	REAR BUMPER INNER FRAME PAD (N)	CRACKED	285.00	285.00
1	CONTROL MODULE FOR PARK ASSISTANT KIT (N)	NOT NECESSARY	345.00	-
1	REAR FLOOR BOARD (N)	NOT NECESSARY	310.00	-
2	FRONT SEAT HEAD RESTS (N)	NOT NECESSARY	910.00	-
1	REAR EXHAUST CHROME O/S (N)	BENT	570.00	322.50
	LESS 5% DISCOUNT		-729.75	-
	LESS 10% DISCOUNT		-	-438.70
			13,865.25	3,948.34
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET REAR BUMPER CLIP (SN)	NECESSARY	80.00	50.00
			80.00	50.00

Report Ref No. CS/INC23005993/Uqy3m4



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	TO REMOVE, REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING.		80.00	20.00
	TO REMOVE AND REFIT INNER GARNISHES.		180.00	60.00
	TO REMOVE AND REFIT REAR REVERSE SENSOR.		150.00	50.00
	TO TRANSFER BOOT LID MECHANISM AND WIRING ASSEMBLY.	NOT NECESSARY	120.00	-
	TO APPLY UNDERCOATING.	NOT NECESSARY	200.00	-
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BOOT LID AND REAR END PANEL.		1,500.00	550.00
	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS.		1,400.00	600.00
			3,630.00	1,280.00
<b>GRAND TOTAL</b>			<b>17,575.25</b>	<b>5,278.34</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>4,200.00</b>

Report Ref No. CS/INC23005993/Uqy3m4

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.