

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | | |
|---|--|--|----------------|---------|-----------------------|--|
| | STRIDES AUTOMO | OTIVE SERVICES PTE LTD | | Ref: | CS/SMR23006000/Rnp3m4 | |
| | 60 WOODLANDS I E4SINGAPORE 75 | NDUSTRIAL PARK 37705 | | Date: | 28/06/2023 | |
| | | | | Code: | SMR | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | | |
| | Insured Veh. | SHB 1267K | Veh. Inspected | l | SMN 7263J | |
| | Policy No. | | Coverage (\$) | | 0.00 | |
| | Claim No. | TAX/06/23/2019 | Excess (\$) | | 0.00 | |
| | Assign From | HUA YEN | Assign Date | | 13/06/2023 | |
| 2. | Vehicle Particulars & Condition | | | | | |
| | Make & Model | HYUNDAI AVANTE 1.6 GLS A | c.c | | 1591 | |
| | Engine No. | HIDDEN | Year of Reg. | | 2019 | |
| | Chassis No. | KMHD841CMLU964467 | Colour | | GREY | |
| | Odometer | 92538 KM | Steering | | IN ORDER | |
| | Brakes | IN ORDER | Modification | | SPORTS RIM | |
| | General | FAIR | | | | |
| 3. | 3. Conditions of Tyres | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 205/55R16 | HABILEAD | | 6 mm | |
| | L/H Front Tyre | 205/55R16 | HABILEAD | | 6 mm | |
| | R/H Rear Tyre | 205/55R16 | HABILEAD | | 6 mm | |
| | L/H Rear Tyre | 205/55R16 | HABILEAD | | 6 mm | |
| 4. | Description of Damages | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. | | | | | |
| | DAMAGES SEE DETAILS. | | | | | |
| 5. | General Information | | | | | |
| | Accident Date | 08/06/2023 | Inspection Dat | е | 13/06/2023 | |
| | Survey held at | R&S AUTOCLAIM PTE LTD | - | | | |
| | | 13 PIONEER SECTOR 1, SINGAPORE 628424 | | | | |
| 5a. | Remarks | | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |
| 5b. | Estimate Days of Repair | | | | | |
| | ESTIMATED NORI | MAL PERIOD FOR REPAIR: | | 5 Worki | ng Days | |