

(08/11/13) Wef

ASS. REC. BY: /

Tanjil

REF:

CS/HUA 23006011/tnj3

**ASSIGNMENT**

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lump Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Lim TS

Veh No:

SUA 5981K

Yr Regn:

2019, July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai

c.c.

1580

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

346479

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

UMH 85/CVKA 164543

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

-

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Weslake

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

14/6/23

Survey held at

Comfort Lodge

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt + N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$ )

Add Fee:

☐

Site Insp (\$ )

☐

Interview (\$ )

☐

Tech. Invs (\$ )

☐

Weekend (\$ )

**ComfortDelGro Engineering Pte Ltd** (Co.Reg.No:199506048W)59 Loyang Drive  
Singapore 508969  
Tel: 6214 8300

Lim Tien Siong

**TP INSURER:**  
**CTPL****HL Assurance Pte Ltd (HQ)**

CL(S)

LKK-

Singapore

**PARTICULARS OF CLAIM**

|                               |                                            |                    |                   |
|-------------------------------|--------------------------------------------|--------------------|-------------------|
| Claim Type:                   | THIRD PARTY                                | Ref. No:           |                   |
| Policy No:                    |                                            | Date of Loss:      | 12/06/2023        |
| Vehicle Reg. No.:             | <b>SHA5981K</b>                            | Driveable?         |                   |
| Party At Fault:               | UNKNOWN                                    |                    |                   |
| Make/Model:                   | HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)      | Vehicle Reg. Date: | 02/07/2019        |
| Vehicle Colour:               | BLUE                                       | Chassis No:        | KMHC851CVKU164543 |
| Engine No:                    | G4LEKU296306                               |                    |                   |
| Odometer:                     | 0 KM                                       |                    |                   |
| Paint Type:                   |                                            |                    |                   |
| List Item Discount:           | 20.00 %                                    |                    |                   |
| Total Loss?                   | <b>NO</b>                                  |                    |                   |
| Est. Duration of Repair (day) | 3                                          |                    |                   |
| Present Location:             | COMFORTDELGRO ENGINEERING PTE LTD (LOYANG) |                    |                   |

**COST OF CLAIMS**

|                          | <b>Amount</b>   |
|--------------------------|-----------------|
| Parts                    | 3,257.72        |
| Miscellaneous Items      | 0.00            |
| Labour                   | 1,480.00        |
| Paintwork Labour         | 0.00            |
| Towing                   | 0.00            |
| <b>Gross Total (S\$)</b> | <b>4,737.72</b> |
| <b>+ GST 8.00% (S\$)</b> | <b>379.02</b>   |
| <b>Nett Amount (S\$)</b> | <b>5,116.74</b> |

**This claim is handled by: LIM TIEN SIONG**

Generated using Merimen e-Claims Internet Estimation &amp; Adjusting System

13/6 @ 16:15 hrs.

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 13 Jun 2023)  
**Parts:** 192      HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)  
**Labour:** Repairer's      (Price-denominated Standard List)

Lim Tien Siong

**Print Code:** ComfortDelGro Engineering Pte Ltd/SHA5981K/13/06/2023 16:15

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Estimates on Parts

| No.                                   | Qty | Part No. | Particulars                 | %Disc | %Depr | Amount           |
|---------------------------------------|-----|----------|-----------------------------|-------|-------|------------------|
| 1                                     | 1   |          | *FRT BUMPER                 | 20.00 | 0.00  | de ✓ *481.10 FL  |
| 2                                     | 1   |          | *FRT BUMPER UPPER MOULDING  | 20.00 | 0.00  | x ✓ *368.50 FL   |
| 3                                     | 10  |          | *FRT BUMPER CLIPS           | 20.00 | 0.00  | ue ✓ *22.00 FL   |
| 4                                     | 1   |          | *FRT BUMPER SIDE BRKT LH    | 20.00 | 0.00  | x ✓ *35.00 FL    |
| 5                                     | 1   |          | *HEADLAMP LH                | 20.00 | 0.00  | ? ✓ *2,110.30 FL |
| 6                                     | 1   |          | *DAYLIGHT GRILLE LH         | 20.00 | 0.00  | cut ✓ *93.45 FL  |
| 7                                     | 1   |          | *FRT FENDER LH              | 20.00 | 0.00  | bc ✓ *588.80 FL  |
| 8                                     | 1   |          | *FRT FENDER (BLUE-DRIVE) LH | 20.00 | 0.00  | ue ✓ *26.60 FL   |
| 9                                     | 1   |          | *FRT WHEEL CAP LH           | 20.00 | 0.00  | cut ✓ *346.40 FL |
| Sub Total (S\$)                       |     |          |                             |       |       | 4,072.15         |
| - List Item Discount on L Items (S\$) |     |          |                             |       |       | 814.43           |
| Total Parts (S\$)                     |     |          |                             |       |       | 3,257.72         |

F=Franchise part, L=ListItemDisc.

ComfortDelGro Engineering Pte Ltd/SHA5981K/13/06/2023 16:15. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Lim Tien Siong

## Estimates on Labour

| No                              | Particulars     | Lab.Type | Amount          |
|---------------------------------|-----------------|----------|-----------------|
| <b>Labour Items</b>             |                 |          |                 |
| 1                               | PANEL BEATING   | New 350  | 800.00          |
| 2                               | SPRAY PAINTING  | New 500  | 600.00          |
| 3                               | CHECK LIGHTINGS | New 30?  | 40.00           |
| 4                               | TUFF KOTE       | New 30   | 40.00           |
| <b>Gross Labour Cost (\$\$)</b> |                 |          | <b>1,480.00</b> |

ComfortDelGro Engineering Pte Ltd/SHA5981K/13/06/2023 16:15. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Templin 9744 5744  
'wp' 14/6/23 @ 4pm  
L/S Resury after repair  
Templin / Kuantan.  
2 days

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5900102

JC NO305557620

OMER

S COMFORT TRANSPORTATION PTE LTD  
OMER NO. 7010045  
ESS 383 SIN MING DRIVE  
Singapore SINGAPORE 575717  
(R) 65508755 (O)

JUNT CARD NO.

REGN NO.:

SHA5981K

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G2)

DATE/TIME IN 13.06.2023 13:40

YR OF MANU

02.07.2019

TARGET DATE

CHASSIS CODE

KMHC851CVKU164543


COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 12.06.2023  
ATURE: 3P 12.06.2023/C

NO LABOR CODE  
0010 PB

DESCRIPTION  
PANEL BEATING-SHA5981K-TP



LED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Idgement Slip

Exit Pass

o.: SHA5981K LIMITS

Vehicle No.: SHA5981K

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard