

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURA	NCE BHD		Ref:	CS3/LPC23006012/Kvy3e2	
	300 BEACH ROAD SINGAPORE 1995		Date:	19/06/2023		
				Code:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	GR 663J	Veh. Inspected	I	SMC 5849R	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	22/23/23/VC05/027546	Excess (\$)		0.00	
	Assign From	CHARMAINE KONG	Assign Date		13/06/2023	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA CIVIC (A)	c.c		1498	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	MRHFC1660JT000084	Colour		METALLIC LIGHT GREY	
	Odometer	119619 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	235/45Z R17	TOURADOR		8 mm	
	L/H Front Tyre	235/45Z R17	TOURADOR		8 mm	
	R/H Rear Tyre	235/45Z R17	TOURADOR		8 mm	
	L/H Rear Tyre	235/45Z R17	TOURADOR		8 mm	
4.	4. Description of Damages					
	THE VEHICLE SU	HICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5.	General Information					
	Accident Date	12/06/2023	Inspect Date /	Time	14/06/2023 ( 10:37 AM )	
	Survey held at	WAH YU AUTOMOTIVE BODY WORK				
		176 SIN MING DRIVE #05-09 SINGAPORE 575721				
5a. Remarks						
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC23006012/Kvy3e2

Inspected By

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

**REGD Auto Consultant-SAE, Licensed Appraiser**