

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/III23002118/RVY3E2-1**Date:** 18/07/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_02
Claimant Vehicle No : SNC8018R **Insured Vehicle No :** SLL681D
 Date of Loss: 23/02/2023 Nature of Claim: TP Claim No: MFL2023D0002377

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNC8018R**
 Make & Model: HONDA FIT, 1.5 (A) Engine No: LEB1436328
 Reg. Date: 22/11/2018 (Man. Year: 2018) Chassis No: GP51330187
 Colour: Blue Odometer: 0 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
 Front Left Side: KAPSEN 6 mm Rear Left Side: KAPSEN 6 mm
 Front Right Side: KAPSEN 6 mm Rear Right Side: KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,668.32	12,525.31	6,143.01	32.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,100.00	4,290.00	3,810.00	47.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,768.32	16,815.31	9,953.01	37.18
Approved Total (Overridden) (S\$)		13,450.00		
Nett Amount (S\$)	26,768.32	13,450.00	13,318.32	49.75

INSPECTION

Date of Assignment: 13/06/2023
 Date Inspected: 27/02/2023 Inspected At: JCM Rental Pte Ltd (HQ)
 1 Bukit Batok Crescent, #04-40 Wcega Plaza
 Singapore 658064
 Estimated Period of Repair: 12.0 days

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Jul 2023)
Parts:	144	HONDA FIT 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNC8018R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deep Cut	713.80 FL	*713.80 FL
2	1		*FRONT BUMPER SIDE RETAINER	Not Necessary	30.80 FL	*- FL
3	1		*FRONT LH FENDER	Not Necessary	348.60 FL	*- FL
4	1		*FRONT LH FENDER INNER SHIELD	Not Necessary	86.80 FL	*- FL
5	1		*REAR BUMPER	Dented	496.90 FL	*496.90 FL
6	1		*REAR BUMPER CENTER GARNISH	Deformed	87.80 FL	*87.80 FL
7	1		*REAR BUMPER SIDE GARNISH (2PCS)	Deformed (1Pc Only)	156.00 FL	*78.00 FL
8	1		*REAR BUMPER REFLECTOR	O/S Broken	50.80 FL	*25.40 FL
9	2		*REAR BUMPER RETAINER	Torn	50.80 FL	*50.80 FL
10	1		*REAR BUMPER SPONGE	N/S Missing	163.80 FL	*65.00 FL
11	1		*TAILLAMP	O/S Broken	1,014.40 FL	*322.20 FL
12	1		*TAILGATE	Dented	1,209.10 FL	*860.00 FL
13	1		*TAILGATE EMBLEM FIT	Necessary	35.10 FL	*35.10 FL
14	1		*TAILGATE EMBLEM HYBRID	Necessary	74.10 FL	*74.10 FL
15	2		*TAILGATE REFLECTOR	Not Necessary	937.60 FL	*- FL
16	1		*TAILGATE INNER LOCK	Dented	117.00 FL	*117.00 FL
17	1		*TAILGATE OUTER CHROME	Not Necessary	327.60 FL	*- FL
18	1		*TAILGATE INNER RUBBER	Kinded	97.50 FL	*97.50 FL
19	1		*TAILGATE INNER TRIM	Deformed	120.90 FL	*120.90 FL
20	1		*TAILGATE INNER PULL POCKET	Not Necessary	15.60 FL	*- FL
21	1		*REAR END PANEL	Dented	487.50 FL	*420.00 FL
22	1		*REAR END PANEL INNER TRIM	Deformed	165.80 FL	*165.80 FL
23	1		*REAR FENDER	O/S Dented	1,658.00 FL	*685.60 FL
24	1		*REAR FENDER INNER TRIM	O/S Deformed	460.20 FL	*205.10 FL
25	1		*REAR WINDSCREEN	Shattered	1,072.50 FL	*949.44 FL
26	1		*REAR WINDSCREEN MOULDING	Necessary	97.50 FL	*97.50 FL
27	1		*HYBRID BATTERY	Dented	9,803.50 FL	*8,000.00 FL
28	1		*HYBRID BATTERY INLET DUCT	Deformed	253.80 FL	*129.65 FL
29	1		*HYBRID BATTERY OUTLET DUCT	Deformed	185.30 FL	*63.15 FL
30	1		*KEYLESS ANTENNA	Not Necessary	93.60 FL	*- FL
31	1		*KEYLESS BUZZER	Not Necessary	126.80 FL	*- FL
32	1		*SETS FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
33	1		*SETS FRONT LH FENDER INNER SHIELD CLIPS	Necessary	80.00 FS	*30.00 FS
34	1		*SETS REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
35	2		*SETS REAR FENDER INNER TRIM CLIPS	Necessary	160.00 FS	*60.00 FS
36	1		*SETS REAR END PANEL TRIM CLIPS	Necessary	60.00 FS	*30.00 FS
37	1		*SETS REVERSE SENSOR	Dented	250.00 FS	*200.00 FS
38	1		*SETS REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
39	1		*SETS REAR WINDSCREEN INNER SEAL	Necessary	60.00 FS	*20.00 FS
40	1		*SETS REAR WINDSCREEN PRIMER	Necessary	80.00 FS	*40.00 FS
41	1		*SETS REAR END PANEL SEALANT	Necessary	80.00 FS	*40.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*SETS TAILGATE SEALANT	Necessary	80.00 FS	*40.00 FS
43	1		*SETS REAR LH FENDER SEALANT	Not Necessary	80.00 FS	*- FS
44	1		*PHV STICKER	Necessary	30.00 FS	*30.00 FS
45	1		*REAR WINDSCREEN SOLAR FILM	Necessary	300.00 FS	*150.00 FS
46	1		*SPARE TYRE PANEL	Dented	820.90 FL	*820.90 FL
47	1		*SETS REAR RH FENDER SEALANT	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	22,940.40	15,461.64
- List Item Discount on L Items 20.00/20.00% (\$)	4,272.08	2,936.33
Total Parts (\$)	18,668.32	12,525.31

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING SYSTEM	New	100.00	30.00
2	TO REPROGRAMME AND RESET AFTER REPAIR	New	200.00	100.00
3	TO R&R HYBRID BATTERY AND RESET THE SYSTEM	New	500.00	200.00
4	TO R&R REAR WINDSCREEN GLASS	New	200.00	120.00
5	TO R&R REAR TRIMMING AND CARPET FOR HOT WORK REPAIR	New	200.00	100.00
6	TO R&R REAR EXHAUST PIPE AND REALIGN THE SAME	New	150.00	60.00
7	TO TRANSFER TAILGATE ATTACHMENTS	New	150.00	60.00
8	TO R&R FUEL TANK FOR HOT WORK REPAIR	New	100.00	0.00
9	TO R&R FRONT BUMPER, FRONT LH FENDER AND REALIGN THE SAME	New	500.00	300.00
10	TO PUTTY AND RESPRAY ON FRONT BUMPER, FRONT LH FENDER AND ACCIDENT AFFECTED AREAS	New	800.00	400.00
11	TO CUT & WEILD ON REAR BOTH FENDER, SPARE TYRE PANEL, REAR END PANEL. TO PANEL BEAT & STRAIGHTEN ON REAR CHASSIS MEMBER. TO R&R REAR BUMPER, TAILGATE, TAILLAMP OTHERS ATTACHEMENTS	New	3,000.00	1,400.00
12	TO PUTTY AND RESPRAY ON REAR BUMPER, TAILGATE, REAR BOTH FENDER, REAR LH DOOR, REAR END PANEL, SPARE TYRE PANEL AND ACCIDENT AFFECTED AREAS	New	2,000.00	1,400.00
13	RUSTPROOFING	New	200.00	120.00
Gross Labour Cost (S\$)			8,100.00	4,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >