

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG23006018/KQY3E2**Date:** 27/06/2023REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1002643312
Claimant Vehicle No :	SMZ7154C	Insured Vehicle No :	SNJ6432D
Date of Loss:	12/06/2023	Nature of Claim:	TP
		Claim No:	317932

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMZ7154C	Engine No:	G4FGKH746545
Make & Model:	KIA CERATO, 1.6 SUNROOF (A)	Chassis No:	KNAF5416MK5051160
Reg. Date:	13/08/2019 (Man. Year: 2019)	Odometer:	128246 km
Colour:	Metallic Pearl White		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	Pirelli 7 mm	Rear Right Side:	Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,158.80	5,018.60	3,140.20	38.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,040.00	2,130.00	1,910.00	47.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,198.80	7,148.60	5,050.20	41.40
Approved Total (Overridden) (S\$)		5,700.00		
Nett Amount (S\$)	12,198.80	5,700.00	6,498.80	53.27

INSPECTION

Date of Assignment:	16/06/2023	
Date Inspected:	14/06/2023	Inspected At: Massive Trading & Auto Blk 5038 #01-405, Ang Mo Kio Industrial Pk 2 Singapore 569541
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Jun 2023)
Parts:	143	KIA CERATO 1.6 SUNROOF (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMZ7154C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR N/S DOOR	Bent	1,385.00 FL	*1,377.00 FL
2	1		*REAR N/S DOOR INNER TRIM BOARD	Mtg Cracked	587.00 FL	*587.00 FL
3	1		*REAR N/S DOOR GLASS REGULATOR	Distorted	255.00 FL	*255.00 FL
4	1		*REAR N/S DOOR GLASS REGULATOR MOTOR	Jammed	405.00 FL	*405.00 FL
5	1		*REAR N/S DOOR INNER LOCK	Repair	287.00 FL	*- FL
6	1		*REAR N/S DOOR RUBBER (50%)	Distorted	225.00 FN	*112.50 F
7	1		*REAR FENDER	Bent	1,183.00 FL	*1,183.00 FL
8	1		*REAR N/S FENDER AIR DUCT	Serviceable	115.00 FL	*- FL
9	1		*REAR N/S FENDER INNER SHIELD	Serviceable	85.00 FL	*- FL
10	1		*REAR N/S FENDER INNER TRIM BOARD	Serviceable	399.00 FL	*- FL
11	1		*REAR WINDSCREEN MOULDING	Necessary	90.00 FL	*90.00 FL
12	1		*REAR BUMPER	Repair	688.00 FL	*- FL
13	1		*REAR N/S BUMPER SIDE RETAINER	Serviceable	85.00 FL	*- FL
14	1		*REAR N/S SHOCK ABSORBER	Serviceable	205.00 FL	*- FL
15	1		*REAR N/S WHEEL HUB	Bent	389.00 FL	*341.00 FL
16	1		*REAR AXLE ASSY	Serviceable	1,049.00 FL	*- FL
17	1		*N/S ROCKER PANEL GARNISH	Mtg Cracked	850.00 FL	*691.00 FL
18	1		*REAR N/S TYRE RIM	Dented	480.00 FS	*400.00 FS
19	1		*REAR N/S DOOR EDGE PROTECTOR	Necessary	120.00 FS	*40.00 FS
20	1		*REAR WINDSCREEN SEALANT	Necessary	30.00 FS	*30.00 FS
21	1		*REAR BUMPER CLIP (30PCS)	Not Necessary	75.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$)	8,987.00	5,511.50
- List Item Discount on L Items 10.00/10.00% (\$)	805.70	492.90
- Nett Item Discount on N Items 10.00/0.00% (\$)	22.50	0.00
Total Parts (\$)	8,158.80	5,018.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE / RENEW THE ABOVE PARTS INCLUDING KNOCKING, CUTTING & WELDING	New	1,500.00	800.00
2	TO PUTTY & SPRAY PAINT ON ACCIDENT AFFECTED PORTION	New	1,200.00	800.00
3	CHECK / RECONNECT WIRING	New	60.00	20.00
4	TO SPRAY ANTI RUST ON ACCIDENT AFFECTED PORTION	New	180.00	60.00
5	REMOVE / RENEW REAR WINDSCREEN TO FACILITATE REPAIR	New	120.00	120.00
6	REMOVE / REFIT ROOF LINING TO FACILITATE REPAIR	New	180.00	100.00
7	REMOVE / REFIT FUEL TANK TO FACILITATE REPAIR	New	120.00	60.00
8	CHECK AND REALIGN WHEEL ALIGNMENT	New	80.00	60.00
9	REMOVE / RENEW REAR N/S DOOR MECHANISM TO NEW DOOR	New	120.00	60.00
10	REMOVE / RENEW REAR UNDERCARRIAGES	New	480.00	50.00
Gross Labour Cost (\$\$)			4,040.00	2,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >