## Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

21 Jun 2023

Attn: Richard Ang Wei Guang

# **Preliminary Advice**

Date:

Insured Vehicle No : SNJ6432D

TP Vehicle No : SMZ7154C Accident Date : 12/06/2023 : 16/06/2023 Make : KIA CERATO Assignment Date

Date of Inspection : 14/06/2023 Est. Duration of Repair : 6

Inspection At : MASSIVE TRADING & AUTO

BLK 5038 #01-405, ANG MO KIO INDUSTRIAL PK 2

SINGAPORE 569541

## Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,198.80 7,148.60	
Revised Amount	:S\$		
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	7,148.60	
Lump Sum Repair	:S\$	5,700.00	

#### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	83,000.00
COE / PARF Rebate	:S\$	34,624.00
Salvage Value	:S\$	
Margin for Repair	:S\$	48,376.00

### Remarks

(		)	The vehicle is economical for repair
(		)	The vehicle is not economical for repair
(		)	Part-by-Part repair
(	Χ	)	Lump Sum repair

The above survey was conducted on a 'without prejudice' basis. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.