



Your Ref : SNM23D201813/C01/TAYHP

Date: 21st Jun 2023

Our Ref : CS/CTI23006021/Uvp3e2

M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SR 89A
ACCIDENT ON 02/03/2023**

Instruction was received to inspect the vehicle Reg. No. SR 89A. The inspection was conducted on 14/06/2023 at the premises of M/s SME Motor Pte Ltd, 1 Kaki Bukit Ave 6 #02-15 (Autobay @Kaki Bukit), Singapore 417883.

The following vehicle information was recorded:

Registration Number	: SR 89A
Make/Model	: B.M.W. X6 M AT ABS D/AB 4WD TC 5DR GAS/D SR HUD
Year of Registration	: 2011
Body Colour	: White
Chassis Number	: WBSGZ02090LJ88980
Engine Capacity	: 4395 cc

The vehicle sustained damages at the front portion. The undercarriage and chassis frame affected due to collision. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 125,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 38,160.00
Nett Liability	<u>S\$ 86,840.00</u> =====

Vehicle Inspected By:



CHUA KANG SENG
Licensed Appraiser



K.K.LAU
MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.