

(08/11/13) wef

ASS. REC. B: Marcus

REF:

CC4/GRB23006023/493

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBT 8354X

at Workshop m/s 10's 320

of \_\_\_\_\_

Insured: SLK 2959X

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 643k.

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

196N

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: LTA 818456

Veh No: GBT 8354X Yr Regn: 23/03/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (M)

Make: Toyota hiace DX c.c. 2982

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 201 827 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KDH 201019 4934

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195-215

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Austone

Front 6 mm Rear 6 mm

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 07/06/23 D.O.I. 14/6/23

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

A20-

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction Day 11k.

28/6/23 1/5 4700 Inform Susan.

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) \_\_\_\_\_



# Liu's Brother Auto Engineering Workshop

No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883

UEN No: 53291793J

liusbro@gmail.com

Tel: 67411730

## ESTIMATE

Name: India International Insurance Pte Ltd  
Address: Motor Claims Department  
64 Cecil Street #04-00 & #05-00  
IOB Building Singapore 049711

Ref Date: 12-06-2023  
Ref No: GBF8354X230607  
Vehicle No: GBF8354X  
Model / Make: Toyota Hiace  
Capacity: 2982 cc DX 3.0 M

| Item # | Damaged Area | Description                                                                     | Unit Price  | Qty | Estimation / Quotation | N / SN | Cost Of Repair |
|--------|--------------|---------------------------------------------------------------------------------|-------------|-----|------------------------|--------|----------------|
| 1      | Rear         | Tailgate                                                                        | \$ 2,051.60 | 1   | \$ 2,051.60            |        | ✓              |
| 2      |              | Tailgate Inner Lock                                                             | \$ 359.00   | 1   | \$ 359.00              |        | ✓              |
| 3      |              | Tailgate Rubber                                                                 | \$ 426.70   | 1   | \$ 426.70              |        | ✓              |
| 4      |              | Tailgate "70 KM/H" Sticker                                                      | \$ 15.00    | 1   | \$ 15.00               | SN     | 10 S/N         |
| 5      |              | Tailgate "8 PAX" Sticker                                                        | \$ 15.00    | 1   | \$ 15.00               | SN     | 10 S/N         |
| 6      |              | Tailgate "Toyota Logo" Motif                                                    | \$ 167.00   | 1   | \$ 167.00              |        | ✓              |
| 7      |              | Number Plate & Base                                                             | \$ 48.00    | 1   | \$ 48.00               | SN     | X              |
| 8      |              | Tailgate Windscreen Glass Moulding                                              | \$ 219.00   | 1   | \$ 219.00              |        | X              |
| 9      |              | Tailgate Windscreen Glass Sealant                                               | \$ 50.00    | 1   | \$ 50.00               | SN     | 40 S/N         |
| 10     |              | Bumper                                                                          | \$ 599.30   | 1   | \$ 599.30              |        | ✓              |
| 11     |              | Bumper Clips 1 set                                                              | \$ 48.00    | 1   | \$ 48.00               | SN     | ✓ S/N          |
| 12     | 1 set        | Bumper Reverse Sensor                                                           | \$ 220.00   | 1   | \$ 220.00              | SN     | 200 S/N        |
| 13     |              | Bumper Step Panel                                                               | \$ 362.30   | 1   | \$ 362.30              |        | ✓              |
| 14     |              | End Panel Inner                                                                 | \$ 936.20   | 1   | \$ 936.20              |        | X              |
| 15     |              | End Panel Outer                                                                 | \$ 566.10   | 1   | \$ 566.10              |        | ✓              |
| 16     |              | End Panel Sealant                                                               | \$ 50.00    | 1   | \$ 50.00               | SN     | ✓ S/N          |
| 17     |              | Spare Tyre Carrier                                                              | \$ 345.20   | 1   | \$ 345.20              |        | X              |
| 18     | Rear Rh      | Bumper Bracket                                                                  | \$ 202.00   | 1   | \$ 202.00              |        | ✓              |
| 19     |              | Tail Lamp                                                                       | \$ 365.10   | 1   | \$ 365.10              |        | ✓              |
| 20     |              | Corner Panel                                                                    | \$ 185.80   | 1   | \$ 185.80              |        | ✓              |
| 21     |              | "Corporate" Advertisement & Artwork                                             | \$ 300.00   | 1   | \$ 300.00              | SN     | 120 S/N        |
| 22     |              | Remove and refix rear tailgate components & wiper mechanism                     | \$ 80.00    |     | \$ 80.00               |        | 60             |
| 23     |              | Remove & reinstall Tailgate Glass to facilitate repairs                         | \$ 120.00   |     | \$ 120.00              |        | 100            |
| 24     |              | Remove and refix rear bumper reverse sensor                                     | \$ 80.00    |     | \$ 80.00               |        | 50             |
| 25     |              | Labour for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc           | \$ 1,000.00 |     | \$ 1,000.00            |        | 850            |
| 26     |              | To putty & spray painting & including touch up paint on accident affected areas | \$ 700.00   |     | \$ 700.00              |        | 600            |
| 27     |              | To apply Rust Proofing, reseal tuff-coating treatment on accident area          | \$ 50.00    |     | \$ 50.00               |        | ✓              |

366.10

86.00

245.50

105.10

Total Parts & Labour of estimate for damaged vehicle

\$ 9,561.30

Total amount in Parts By Parts Basis for repaired vehicle

SDL

NOP Authn  
14/6/23  
1/5 # 4700  
6 days  
Whipht. Akary

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Liu's Bro Auto Engrg Wks

P- 4928-60  
252  
3697.20  
478  
1710  
5582.20  
203  
4708