

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/III23001409/DQY3E2-1**Date:** 28/06/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0006372_02
Claimant Vehicle No : SJW8012Z **Insured Vehicle No :** SHD2605B
 Date of Loss: 04/02/2023 Nature of Claim: TP Claim No: MFL2023D0001721

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJW8012Z**
 Make & Model: MITSUBISHI LANCER, 1.6 EX AT LED TAIL LAMP (A) Engine No: 4A92CN7595
 Reg. Date: 02/05/2017 (Man. Year: 2016) Chassis No: JMYSRCY1AGU006543
 Colour: Blue Odometer: 93587 km
 Engine Capacity: 1590 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
 Front Left Side: Falken 5 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Falken 5 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,455.00	1,684.10	2,770.90	62.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,700.00	1,260.00	1,440.00	53.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,155.00	2,944.10	4,210.90	58.85
Approved Total (Overridden) (S\$)		2,350.00		
Nett Amount (S\$)	7,155.00	2,350.00	4,805.00	67.16

INSPECTION

Date of Assignment: 15/06/2023
 Date Inspected: 10/02/2023 Inspected At: Sin Heng Long Motor Work (Ang Mo Kio)
 Estimated Period of Repair: 5.0 days Blk 5032 Ang Mo Kio Industrial Park 2, #01-305
 Singapore 569535

Adjuster: BRYAN TANI**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Jun 2023)
Parts:	143	mitsubishi LANCER 1.6 EX AT LED TAIL LAMP (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJW8012Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Not Necessary	595.00 F	*- FL
2	1		*REAR BOOT LID LOGO STAR	Necessary	35.00 F	*35.00 FL
3	1		*REAR BOOT LID EMBLEM EX	Necessary	29.00 F	*29.00 FL
4	1		*REAR BOOT LID EMBLEM LANCER	Necessary	40.00 F	*40.00 FL
5	2		*REAR BOOT LID EMBLEM MIVEX	Necessary	42.00 F	*42.00 FL
6	1		*REAR BOOT LID REFLECTOR LAMP RH	Not Necessary	127.00 F	*- FL
7	1		*REAR BOOT LID INNER TRIM	Not Necessary	148.00 F	*- FL
8	10		*REAR BOOT LID INNER TRIM CLIP	Not Necessary	30.00 F	*- FL
9	2		*REAR BOOT LID DAMPER RH/LH	Not Necessary	100.00 F	*- FL
10	2		*REAR BOOT LID HINGE RH/LH	Not Necessary	144.00 F	*- FL
11	1		*REAR BOOT LID LOCK	Not Necessary	130.00 F	*- FL
12	1		*REAR BOOT LID LOCK CATCH	Not Necessary	35.00 F	*- FL
13	1		*REAR BOOT WEATHERSTRIP	Deformed	142.00 F	*142.00 FL
14	2		*REAR TAIL LAMP RH / LH	Not Necessary	608.00 F	*- FL
15	1		*REAR BUMPER	Squashed	724.00 F	*724.00 FL
16	1		*REAR BUMPER REFLECTOR RH/LH	N/S Fractured	76.00 F	*38.00 FL
17	1		*REAR BUMPER TOW COVER	Deformed	15.00 F	*15.00 FL
18	2		*REAR BUMPER NUMBER PLATE LAMP BRACKET RH/LH	Bent	24.00 F	*24.00 FL
19	2		*REAR BUMPER NUMBER PLATE LAMP RH/LH	Fractured	56.00 F	*56.00 FL
20	1		*REAR BUMPER CENTRE BEAM	Bent	63.00 F	*63.00 FL
21	2		*REAR BUMPER IMPACT BRACKET RH / LH	Bent	82.00 F	*82.00 FL
22	1		*REAR BUMPER REINFORCEMENT	Bent	172.00 F	*172.00 FL
23	2		*REAR BUMPER SIDE RETAINER RH/LH	Necessary	58.00 F	*58.00 FL
24	8		*REAR BUMPER CLIP	Necessary	28.00 F	*28.00 FL
25	1		*REAR END PANEL	Repair	463.00 F	*- FL
26	1		*REAR END PANEL INNER TOP GARNISH	Deformed	101.00 F	*101.00 FL
27	1		*REAR BOOT LID EMBLEM C&C	Repeated	38.00 FS	*- FS
28	1		*REVERSE SENSOR	Shorted	350.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,455.00	1,849.00
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	164.90
Total Parts (\$)	4,455.00	1,684.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO STRAIGHTEN AND PANEL BEATING, REAR BOOT FLOOR PANEL, REAR END PANEL AND REAR FRAME MEMBERS. TO REMOVE AND REFIT ABOVE PARTS	New	1,000.00	600.00
2	TO PUTTY, RE-SPRAY PAINTING AND POLISH AFFECTED AREAS	New	1,500.00	600.00
3	TO CHECK AND RECTIFY WIRING SYSTEM	New	80.00	30.00
4	TO RUST PROOF AFFECTED AREAS	New	120.00	30.00
Gross Labour Cost (\$\$)			2,700.00	1,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >