

Report No: 0020-23-SHLM

03 April 2023

ACCIDENT VEHICLE SURVEY REPORT

De Souza Paul Francis
31 Bodmin Drive
Singapore 559630

VEHICLE INFORMATION:

Vehicle Reg No.:	SJW8012Z	Odometer:	3500km
Make & Model:	Mitsubishi Lancer	Colour:	Blue
Chassis number:	JMYSRCY1AGU006543	Date of accident:	04/02/2023
Year of Regn.:	02/05/2017	Date inspected:	08/02/2023
Repairer at:	Sin Heng Long Motor Work Blk 5032 Ang Mo Kio Ind Pk 2 #01-287/305 Singapore 569535		

STATIC CHECKS, where applicable:

Steering :	serviceable
Footbrake :	serviceable
Handbrake :	serviceable
Paintwork :	Good
General condition :	Good

TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
Front:	6mm/Falken	6mm/Falken	205/60R16
Rear:	6mm/Falken	6mm/Falken	205/60R16

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the rear portion.

Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

PAR Automotive Consultancy

Parts and Labour Assessment

Report No: 0020-23-SHLM

Vehicle No: SJW8012Z

Description of part	Qty	Condition as inspected	Repairer's estimate	Our adjustment
Rear boot lid	1	buckled	595.00	nn 595.00 X
Rear boot lid logo "Star"	1	necessary	35.00	35.00 ✓
Rear boot lid emblem "EX"	1	necessary	29.00	29.00 ✓
Rear boot lid emblem "Lancer"	1	necessary	40.00	40.00 ✓
Rear boot lid emblem "Mivex"	2	necessary	42.00	42.00 ✓
Rear boot lid reflector lamp RH	1	reuse	127.00	nn 0.00 X
Rear boot lid inner trim	1	reuse	148.00	nn 0.00 X
Rear boot lid inner trim clip	10	necessary	30.00	nn 30.00 X
Rear boot lid damper RH/LH	2	reuse	100.00	nn 0.00 X
Rear boot lid hinge RH/LH	2	repair	144.00	nn 0.00 X
Rear boot lid lock	1	bent	130.00	nn 130.00 X
Rear boot lid lock catch	1	bent	35.00	nn 35.00 X
Rear boot weatherstrip	1	deformed	142.00	142.00 ✓
Rear tail lamp RH/LH	2	fractured	608.00	nn 608.00 X
Rear bumper	1	squashed	724.00	724.00 ✓
Rear bumper reflector RH/LH	1 2	fractured	76.00	38 76.00
Rear bumper tow cover	1	deformed	15.00	15.00 ✓
Rear bumper number plate lamp bracket RH/LH	2	bent	24.00	24.00 ✓
Rear bumper number plate lamp RH/LH	2	fractured	56.00	56.00 ✓
Rear bumper centre beam	1	bent	63.00	63.00 ✓
Rear bumper impact bracket RH/LH	2	bent	82.00	82.00 ✓
Rear bumper reinforcement	1	bent	172.00	172.00 ✓
Rear bumper side retainer RH/LH	2	necessary	58.00	58.00 ✓
Rear bumper clip	8	necessary	28.00	28.00 ✓
Rear end panel	1	repair	463.00	R 0.00 X
Rear end panel inner top garnish	1	deformed	101.00	101.00 ✓
				1649
				-10%
				1484.10
		Subtotal before discount	4,067.00	3,085.00
Percentage discount	0% and 10%		0.00	308.50
		Sub-total 1	4,067.00	2,776.50
Rear boot lid emblem 'C&C'	1	necessary	38.00	Repeated 38.00 X
Reverse sensor	1	shorted	350.00	200 300.00
		Subtotal before discount	388.00	338.00
				200
Percentage discount	0% and 0%		0.00	0.00
		Sub-total 2	388.00	338.00
		Parts-total	4,455.00	3,114.50

PAR Automotive Consultancy

LABOUR

1. To straighten and panel beating, rear boot floor panel, rear end panel and rear frame members. To remove and refit above parts.	1,000.00	600	750.00
2. To putty, re-spray painting and polish affected areas.	1,500.00	600	1,000.00
3. To check and rectify wiring system.	80.00	30	50.00
4. To rust proof affected areas.	120.00	30	60.00
	660		
Labour total	2,700.00		1,860.00
Parts & Labour total	7,155.00		4,974.50

5 days

2344.10

L/S - 1875.28
= 1900

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on LUMP SUM repairs is :
and the recommended number of working days for the repairs is :

\$3,900.00

5


B J Loi (I Eng. MIMI, AIRTE)
Automotive Appraiser